

**Subject:** FW: Graveyard

**HGY/2022/4251 Boundary Wall To Graveyard, Highgate School, North Road**

Repairs to boundary wall including structural elements to ensure safety. Redecoration and repair of railings. Installation of movement monitoring.

0103 Structural Report to support LBC.pdf talks of the problems the tree roots may be causing but there is no Arboricultural Impact Assessment and Method Statement as required by Haringey Council.

Validation Requirements - Arboricultural Impact Assessment and Method Statement.

The trees are clearly marked on the 1869, 25 inch Ordnance Survey Map and thus, presumably, pre-date the walls, which according to the list entry are late 18<sup>th</sup> and early 19<sup>th</sup> century. While the wall “makes an imposing contribution to the centre of Highgate village”, so do the trees. In our view, some way should be found to preserve both trees and wall. There should be an informed consultation between the Tree Officer, a specialist civil engineer and the Conservation Officer

Louise Lewis  
Highgate Neighbourhood Forum