

Grade Defect Report								
	Town or Village	Street	Upstream MH	Downstream MH	Use	Inspection dir.	Observation	Grade
1	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Line deviates left, quarter	0
2	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Material changes, vitrified cl	0
3	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Junction, at 2 o'clock, diame	0
4	london	SOUTHWOOD LANE	MH4	MAIN	Combined	MH4 (D/S) MAIN	Finish node type, manhole r	0
5	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Connection other than juncti	0
6	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Material changes, cast iron	0
7	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Start node type, manhole, re	0
8	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Vermin, rat	0
9	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Connection other than juncti	0
10	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Junction, at 12 o'clock, diam	0
11	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Connection other than juncti	0
12	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Line deviates left, quarter, E	0
13	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Junction, at 2 o'clock, diame	0
14	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Water level, 20% of the verti	0
15	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Water level, 10% of the verti	0
16	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Finish node type, manhole r	0
17	london	SOUTHWOOD LANE	MH3	MH4	Combined	MH4 (U/S) MH3	Start node type, manhole, re	0
18	london	SOUTHWOOD LANE	MH3	MH4	Combined	MH4 (U/S) MH3	Water level, 0% of the vertic	0
19	london	SOUTHWOOD LANE	MH3	MH4	Combined	MH4 (U/S) MH3	Finish node type, manhole r	0
20	london	SOUTHWOOD LANE	MH4	MAIN	Combined	MH4 (D/S) MAIN	Start node type, manhole, re	0
21	london	SOUTHWOOD LANE	MH4	MAIN	Combined	MH4 (D/S) MAIN	Water level, 5% of the vertic	0
22	london	SOUTHWOOD LANE	MH4	MAIN	Combined	MH4 (D/S) MAIN	Line deviates right, quarter	0
23	london	SOUTHWOOD LANE	MH4	MAIN	Combined	MH4 (D/S) MAIN	Line deviates down, full	0
24	london	SOUTHWOOD LANE	MH4	MAIN	Combined	MH4 (D/S) MAIN	Line deviates right, quarter	0
25	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Line deviates left, quarter, St	0
26	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 3 o'cl	2
27	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 12 o'c	2
28	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 11 o'c	2
29	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 12 o'c	2
30	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine, End	2
31	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine, Start	2
32	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine at joint	2
33	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine at joint	2
34	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 3 o'cl	2
35	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 12 o'c	2
36	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, circumferential, from	2
37	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 12 o'c	2
38	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine at joint	2
39	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Deformed sewer/drain, 5%	2

Grade Defect Report								
	Town or Village	Street	Upstream MH	Downstream MH	Use	Inspection dir.	Observation	Grade
40	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 8 o'cl	2
41	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 2 o'cl	2
42	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 10 o'c	2
43	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine, Start	2
44	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Settled deposits, fine, 5% cr	2
45	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine, End	2
46	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine at joint	2
47	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine at joint, Start	2
48	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Roots, fine at joint, End	2
49	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 12 o'c	2
50	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 12 o'c	2
51	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Crack, longitudinal, at 8 o'cl	2
52	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Fracture, longitudinal, at 12	3
53	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Fracture, longitudinal, at 2 o'	3
54	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Fracture, circumferential at j	3
55	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Fracture, longitudinal, at 12	3
56	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Fracture, longitudinal, at 3 o'	3
57	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Fracture, longitudinal, at 12	3
58	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Settled deposits, coarse, 10	3
59	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Fracture, circumferential at j	3
60	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Broken pipe, from 2 to 4 o'cl	4
61	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Broken pipe at joint, from 3 t	4
62	london	SOUTHWOOD LANE	MH1	MH2	Combined	MH1 (D/S) MH2	Hole in drain/sewer, at 12 o'	4

Job Number: 13/235

Survey By: PR

Grid Ref: TQ2841487580

Node Number: MH01

Cover Level: 119.3

Location: Southwood Lane, London

Year Laid: Z

Status: PR

Function: FW

Node Type:

Survey Date: 06/01/14

Manufacturer:

Grating:

COVER

Shape: DT

Hinged: N

Lockable: N

Duty:

Size: 600 x 600

Toxic atmos: N

SHAFT

Side Entry:

Regulating Courses: 9

Depth: 720

Size: 600

Vermin: N

CHAMBER

Soffit Type: T

No. of Step Irons: 3

No. of Ladders: 0

No. of Landings: 0

Size: 1200

Const'n Code: BR

Depth: N/A

Depth of Silt:


H of S:

INCOMING PIPES	Pipe	U/S D/S node Reference		Shape	Pipe Size			Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
	A			C	100				CI		1.00	118.3
	B			C	300				VC		3.17	116.13
	C			C	300				VC		3.26	116.04
	D											
	E											
	F											
OUTGOING PIPES	X			C	375				VC		3.29	116.01
	Y											

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover		Irons/Ladders	Y	Shaft		Chamber		Benching		Other	
-------	--	---------------	---	-------	--	---------	--	----------	--	-------	--

Remarks: Step Iron Broken



Job Number: 13/235

Survey By: PR

Grid Ref:

Node Number: MH02

Cover Level:

Location:

Year Laid:

Status:

Function:

Node Type:

Survey Date: 06/01/14

Manufacturer:

Grating:

COVER

Shape:

Hinged:

Lockable:

Duty:

Size:

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth:

Size:

Vermin:

CHAMBER

Soffit Type:

No. of Step Irons:

No. of Ladders:

No. of Landings:

Size:

Const'n Code:

Depth:

Depth of Silt:

H of S:

INCOMING PIPES	Pipe	U/S D/S node Reference		Shape	Pipe Size			Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
	A											
	B											
	C											
	D											
	E											
	F											
OUTGOING PIPES	X											
	Y											

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover		Irons/Ladders		Shaft		Chamber		Benching		Other	
-------	--	---------------	--	-------	--	---------	--	----------	--	-------	--

Remarks:

Not Surveyed as outside
of Survey Area

Job Number: 13/235

Survey By: PR

Grid Ref: TQ2841387521

Node Number: MH03

Cover Level: 124.04

Location: Southwood Lane, London

Year Laid: Z Status: PR Function: FW Node Type: MH Survey Date: 06/01/14

Manufacturer: Grating:

COVER Shape: Hinged: N Lockable: N Duty: M Size: 670x530 Toxic atmos: N

SHAFT Side Entry: N Regulating Courses: 1 Depth: 0.21 Size: 610x460 Vermin: N

CHAMBER Soffit Type: No. of Step Irons: 2 No. of Ladders: No. of Landings:

Size: 870x810 Const'n Code: BR Depth: Depth of Silt: H of S:


INCOMING PIPES	Pipe	U/S D/S node Reference		Shape	Pipe Size		Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
	A			C	100			VC		1.62	122.42
	B			C	100			VC		1.62	122.42
	C			C	100			CI		0.92	123.12
	D			C	1050			VC		1.76	122.28
	E			C	100			CI		1.08	122.96
	F			C	100			VC		1.60	122.44
	G	MH03		C	100			VC		1.76	122.28

OUTGOING PIPES	X			C	150			VC		1.76	122.28
	Y										

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover		Irons/Ladders		Shaft		Chamber		Benching		Other	
-------	--	---------------	--	-------	--	---------	--	----------	--	-------	--

Remarks:



Job Number: 13/235

Survey By: PR

Grid Ref: TQ2841187530

Node Number: MH04

Cover Level: 124.04

Location: Southwood Lane, London

Year Laid: Z

Status: PR

Function: FW

Node Type: MH

Survey Date: 06/01/14

Manufacturer:

Grating:

COVER

Shape: R

Hinged: N

Lockable: N

Duty: H

Size: 740x600

Toxic atmos: N

SHAFT

Side Entry:

Regulating Courses:

Depth:

Size:

Vermin:

CHAMBER

Soffit Type:

No. of Step Irons:

No. of Ladders:

No. of Landings:

Size: 610x410

Const'n Code: BR

Depth:

Depth of Silt:

H of S:

INCOMING PIPES	Pipe	U/S D/S node Reference		Shape	Pipe Size			Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
	A			C	100				PVC		0.71	123.33
	B			C	100				VC		0.65	123.39
	C											
	D											
	E											
	F											
	G											


OUTGOING PIPES


X			C	100				VC		0.79	123.25
Y											

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover		Irons/Ladders		Shaft		Chamber		Benching		Other	
-------	--	---------------	--	-------	--	---------	--	----------	--	-------	--

Remarks:







REPORT INSPECTION


Operator: SB

Report No: 13/235

Date: 06/01/14

Reviewed by: N Carr

Signature:





CCTV Drainage Survey

Expedition Engineering
Highgate School, Dyne House
Southwood Lane, London, N6 5EE

CCTV DRAINAGE SURVEY REPORT



If you have any questions regarding any content in this report or require costs on any remedial works please feel free to contact us on 0114 2513481 or alternatively email us on info@sewersurveysuk.co.uk.

Kind regards

Project-information / Inspection: 1Project name :
Highgate School, Dyne House, SouthProject Number :
16/328Contact :
Anna CollinsDate :
24/02/2017

Client: **Expedition**
Contact Name: **Anna Collins**
Department: **Engineer**
Road: **The Clove Building, 4 Maguire Street**
Town:
County: **London, SE1 2NQ**
Telephone: **0207 3071027**
Fax:
Mobile: **07786 485693**
E-mail: **anna.c@expedition.uk.com**

Site: **Highgate School, Dyne House**
Contact Name: **Anna Collins**
Department: **Engineer**
Road: **14 Southwood Lane**
Town:
County: **London, N6 5EE**
Telephone: **0207 3071027**
Fax:
Mobile: **07786 485693**
E-mail: **anna.c@expedition.uk.com**

Contractor **Sewer Surveys UK Ltd**
Contact Name: **Andrew Froggatt/Simon Bennett**
Department: **Directors**
Road: **Unit 6, Longacre Close**
Town: **Sheffield**
County: **South Yorkshire, S20 3FR**
Telephone: **0114 2513481**
Fax:
Mobile: **07837 768649/07808 220160**
E-mail: **info@sewersurveysuk.co.uk**

Defect Grade Description / Inspection: 1

Project Name : Highgate School, Dyne House, South	Project number : 16/328	Contact : Anna Collins	Date : 24/02/2017
--	----------------------------	---------------------------	----------------------

1:

Brick: No Structural Defects
Pipe: No Structural Defects

Acceptable Structural Condition

2:

Brick: Minor cracking, Surface mortar loss, Spalling slight, wear slight
Pipe: Circumfrential crack, Moderate joint defects, Spalling slight, Wear slight

Minor collapse risk in short term but potential for further deterioration

3:

Brick: Total mortarloss without other defects, single brick displaced, Deformation up to 5%, Spalling medium, Wear medium
Pipe: Fractures with deformation up tp 5%, Longitudinal cracking or mulitlpe cracking, Minor loss of level, More severe joint

! Collapse unlikely in near future but future deterioration likely !

4:

Brick: Total mortarloss with deformation greater than 10%, Deformation up to 10% and fractured, Displaced/hanging brickwork, Small number of missing bricks
Pipe: Broken, Deformation up to 10% and broken,, Fractured with deformation 5 - 10%, Multipl

!! Collapse likely in foreseeable future !!

5:

Brick: Already Collapsed, Missing invert, Deformation over 10% and fractured, Displaced/hanging brickwork and deformation over 10%, Extensive missing bricks
Pipe: Already collapsed, Deformation over 10% and broken, Extensive areas of fabric missin

!!! Collapsed or collapse imminent !!!

Inspection report / Inspection: 1

Date : 15/01/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 1	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : MH01
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH02
Inspection Direction: MH01 (D/S) MH02	Pipe Length	D/S Depth :

Use: Combined	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Vitrified clay
Total length : 15.50 m	Lining :

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH01	0
	0.00	WL	Water level, 05% of the vertical dimension	0
	0.50	S01	Attached deposits, grease, from 7 to 5 o'clock, 5% cross-sectional area loss, Start	3
	0.50	S02	Settled deposits, fine, 10% cross-sectional area loss, Start	3
	2.20	DEEJ	Attached deposits, encrustation at joint, from 7 to 5 o'clock 10% cross-sectional area loss	3
	2.20	F02	Settled deposits, fine, 10% cross-sectional area loss, End	3
	2.20	CCJ	Crack, circumferential at joint, from 9 to 3 o'clock	2
	2.90	S03	Attached deposits, encrustation at joint, from 7 to 5 o'clock 5% cross-sectional area loss, Start	3
	6.40	JN	Junction, at 10 o'clock, diameter 100mm	0
	7.00	WL	Water level, 15% of the vertical dimension	0
	8.30	DES	Settled deposits, fine, 15% cross-sectional area loss	3
	9.70	LL	Line deviates left, quarter	0
	10.40	CCJ	Crack, circumferential at joint, from 11 to 3 o'clock	2
	12.50	LR	Line deviates right, quarter	0
	13.00	LL	Line deviates left, quarter	0



8.3 m

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/01/2017

Section number :
1

PLR Suffix :
X



Photo: 1_11A

8.3m, Settled deposits, fine, 15% cross-sectional area loss


Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 2	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : MH02
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH03
Inspection Direction: MH03 (U/S) MH02	Pipe Length	D/S Depth :

Use: Combined	Pipe shape : Circular
Year laid : Z	Pipe size : 150 mm
Purpose : Routine inspection of condition	Pipe material : Vitrified clay
Total length : 8.70 m	Lining :

Comment :

1:500	Position	Code	Observation	Grade					
									
	0.00	MH	Start node type, manhole, reference number : MH03	0					
	0.00	WL	Water level, 05% of the vertical dimension	0					
	0.50	S01	DEG Attached deposits, grease, from 7 to 5 o'clock, 5% cross-sectional area loss, Start	3					
	2.10	S02	DEEJ Attached deposits, encrustation at joint, from 7 to 5 o'clock3 5% cross-sectional area loss, Start	3					
	3.50	CMJ	Cracks, multiple at joint, from 7 to 5 o'clock Remarks: Clocks vary	3					
	5.20	CLJ	Crack, longitudinal at joint, at 2 o'clock	2					
	5.20	CLJ	Crack, longitudinal at joint, at 3 o'clock	2					
	8.70	F01	DEG Attached deposits, grease, from 7 to 5 o'clock, 5% cross-sectional area loss, End	3					
	8.70	F02	DEEJ Attached deposits, encrustation at joint, from 7 to 5 o'clock3 5% cross-sectional area loss, End	3					
	8.70	MHF	Finish node type, manhole reference number: MH02	0					
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
3	0	0	0	1	2	2	1.89	16.4	3


Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 3	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH02 (U/S) A Pipe	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	A Pipe MH02
---	---	---	--	----------------------------------

Use: Year laid : Purpose : Total length :	Combined Z Routine inspection of condition 6.60 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 150 mm Vitrified clay
--	--	--	---

Comment :


1:500	Position	Code	Observation	Grade					
									
	0.00	MH	Start node type, manhole, reference number : MH02	0					
	0.00	WL	Water level, 05% of the vertical dimension	0					
	2.50	JN	Junction, at 12 o'clock, diameter 100mm	0					
	3.20	DEEJ	Attached deposits, encrustation at joint, from 7 to 5 o'clock 05% cross-sectional area loss	3					
	3.40	JN	Junction, at 11 o'clock, diameter 100mm	0					
	4.10	JN	Junction, at 11 o'clock, diameter 100mm	0					
	5.40	JN	Junction, at 9 o'clock, diameter 100mm	0					
	6.60	LU	Line deviates up, half	0					
	6.60	OCF	Finish node type, other special chamber reference number: A Pipe Remarks: Possible downpipe	0					
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	1	0	0	0	1

Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 4	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH03 (D/S) MH04	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH03 MH04
Use: Year laid : Purpose : Total length :	Combined Z Routine inspection of condition 25.90 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 150 mm Vitrified clay 	

Comment :

1:500	Position	Code	Observation	Grade	
	0.00	MH	Start node type, manhole, reference number : MH03	0	
	0.00	WL	Water level, 05% of the vertical dimension	0	
	0.50	S01	Attached deposits, grease, from 7 to 5 o'clock, 5% cross-sectional area loss, Start	3	
	17.15	FC	Fracture, circumferential, from 8 to 3 o'clock	3	
	17.15	RF	Roots, fine	2	
	17.40	CN	Connection other than junction, at 11 o'clock, diameter 100mm	0	
	17.40	FL	Fracture, longitudinal, at 3 o'clock	3	
	18.30	FL	Fracture, longitudinal, at 4 o'clock	3	
	20.10	CC	Crack, circumferential, from 8 to 4 o'clock	2	
	21.40	CLJ	Crack, longitudinal at joint, at 9 o'clock	2	
	22.50	FCJ	Fracture, circumferential at joint, from 7 to 5 o'clock	3	
	22.50	FLJ	Fracture, longitudinal at joint, at 12 o'clock	3	
	22.50	RF	Roots, fine	2	
	25.00	FL	Fracture, longitudinal, at 12 o'clock	3	

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/02/2017

Section number :
4

PLR Suffix :
X



Photo: 4_4A

17.15m, Fracture, circumferential, from 8 to 3 o'clock



Photo: 4_7A

17.4m, Fracture, longitudinal, at 3 o'clock

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/02/2017

Section number :
4

PLR Suffix :
X



Photo: 4_8A
18.3m, Fracture, longitudinal, at 4 o'clock



Photo: 4_11A
22.5m, Fracture, circumferential at joint, from 7 to 5 o'clock

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/02/2017

Section number :
4

PLR Suffix :
X



Photo: 4_12A
22.5m, Fracture, longitudinal at joint, at 12 o'clock



Photo: 4_14A
25m, Fracture, longitudinal, at 12 o'clock

Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 5	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH03 (U/S) RWP01	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	RWP01 MH03
---	--	---	--	---

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 4.00 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Vitrified clay
--	---	--	---

Comment :

1:500

Position

Code

Observation

Grade

MH03

0.00

MH

Start node type, manhole, reference number : MH03

0

RWP01

0.00

WL

Water level, 05% of the vertical dimension

0

0.50

S01

DES

Settled deposits, fine, 5% cross-sectional area loss, Start

2

4.00

F01

DES

Settled deposits, fine, 5% cross-sectional area loss, End

2

4.00

OCF

Finish node type, other special chamber reference number: RWP01

0

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	1	1	0.88	3.5	2


Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 6	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH03 (U/S) Gully	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	Gully MH03
---	--	---	--	---------------------------------

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 26.20 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Vitrified clay
--	--	--	---

Comment :

1:500	Position	Code	Observation	Grade					
									
	0.00	MH	Start node type, manhole, reference number : MH03	0					
	0.00	WL	Water level, 05% of the vertical dimension	0					
	2.00	S01 DEEJ	Attached deposits, encrustation at joint, from 7 to 5 o'clock, 5% cross-sectional area loss, Start						
	7.30	JN	Junction, at 9 o'clock, diameter 100mm	0					
	14.90	JN	Junction, at 10 o'clock, diameter 100mm	0					
	23.20	LL	Line deviates left, quarter	0					
	26.20	JN	Junction, at 9 o'clock, diameter 100mm	0					
	26.20	REM	General remark Remarks: Gully in view	0					
	26.20	F01 DEEJ	Attached deposits, encrustation at joint, from 7 to 5 o'clock3 5% cross-sectional area loss, End						
	26.20	GYF	Finish node type, gully reference number: Gully Remarks: 0 Gully in view						
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade


Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 7	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH05 (D/S) MH06	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH05 MH06 MH06
---	---	---	--	---

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 15.10 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Vitrified clay
--	--	--	---

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH05	0
	0.00	WL	Water level, 00% of the vertical dimension	0
	4.60	DEEJ	Attached deposits, encrustation at joint, from 7 to 5 o'clock 05% cross-sectional area loss	3
	4.60	FCJ	Fracture, circumferential at joint, from 7 to 5 o'clock	3
	6.00	FCJ	Fracture, circumferential at joint, from 10 to 3 o'clock	3
	7.50	REM	General remark Remarks: Pushing stone	0
	8.30	FCJ	Fracture, circumferential at joint, from 9 to 3 o'clock	3
	15.10	MHF	Finish node type, manhole reference number: MH06	0



4.6 m



6 m



8.3 m

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
3	0	0	0	1	1	0	0	0	1

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/02/2017

Section number :
7

PLR Suffix :
X



Photo: 7_4A

4.6m, Fracture, circumferential at joint, from 7 to 5 o'clock



Photo: 7_5A

6m, Fracture, circumferential at joint, from 10 to 3 o'clock

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/02/2017

Section number :
7

PLR Suffix :
X



Photo: 7_7A

8.3m, Fracture, circumferential at joint, from 9 to 3 o'clock


Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 8	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : MH04
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH07
Inspection Direction: MH04 (D/S) MH07	Pipe Length	D/S Depth :

Use: Combined	Pipe shape : Circular
Year laid : Z	Pipe size : 150 mm
Purpose : Routine inspection of condition	Pipe material : Vitrified clay
Total length : 17.40 m	Lining :

Comment :

1:500	Position	Code	Observation	Grade
		MH	Start node type, manhole, reference number : MH04	0
	0.00	WL	Water level, 05% of the vertical dimension	0
	0.50	S01	DEG Attached deposits, grease, from 7 to 5 o'clock, 5% cross-sectional area loss, Start	3
	0.50	S02	DEEJ Attached deposits, encrustation at joint, from 7 to 5 o'clock 5% cross-sectional area loss, Start	3
	2.50	DEEJ	Attached deposits, encrustation at joint, from 7 to 5 o'clock 15% cross-sectional area loss	3
	2.60	RFJ	Roots, fine at joint	2
	3.90	RT	Roots, tap Remarks: From break	4
	3.90	B	Broken pipe, from 7 to 5 o'clock	4
	6.50	CL	Crack, longitudinal, at 12 o'clock	2
	6.50	CC	Crack, circumferential, from 12 to 4 o'clock	2
	10.30	F02	DEEJ Attached deposits, encrustation at joint, from 7 to 5 o'clock 5% cross-sectional area loss, End	3
	14.60	B	Broken pipe, from 7 to 5 o'clock	4
	14.60	RFJ	Roots, fine at joint	2



Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/02/2017

Section number :
8

PLR Suffix :
X



Photo: 8_7A
3.9m, Roots, tap Remarks: From break



Photo: 8_12A
14.6m, Broken pipe, from 7 to 5 o'clock


Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 9	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH08 (D/S) MH06	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH08 MH06
---	---	---	--	--

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 23.31 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Vitrified clay
--	--	--	---

Comment :

1:500	Position	Code	Observation	Grade	
	MH08	MH	Start node type, manhole, reference number : MH08	0	
	0.00	WL	Water level, 0% of the vertical dimension	0	1.4 m
	0.00	DES	Settled deposits, fine, 10% cross-sectional area loss	3	
	1.40	DES	Settled deposits, fine, 30% cross-sectional area loss	4	3.81 m
	2.40	DES	Settled deposits, fine, 25% cross-sectional area loss	4	
	3.81	DER	Settled deposits, coarse, 60% cross-sectional area loss (pushing)	4	6.17 m
	6.17	FC	Fracture, circumferential, from 12 to 12 o'clock	3	
	10.19	CCJ	Crack, circumferential at joint, from 7 to 5 o'clock	2	
	10.56	CCJ	Crack, circumferential at joint, from 10 to 4 o'clock	2	
	23.31	MHF	Finish node type, manhole reference number: MH06	0	

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
3	40	1.72	40	3	4	8	0.86	20	4

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/02/2017

Section number :
9

PLR Suffix :
X



Photo: 9_4A

1.4m, Settled deposits, fine, 30% cross-sectional area loss



Photo: 9_6A

3.81m, Settled deposits, coarse, 60% cross-sectional area loss
(pushing)

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
15/02/2017

Section number :
9

PLR Suffix :
X



Photo: 9_7A

6.17m, Fracture, circumferential, from 12 to 12 o'clock

Inspection report / Inspection: 1

Date : 15/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 10	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH06 (D/S) MH09	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH06 MH09
---	---	---	--	--

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 9.13 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 150 mm Vitrified clay
--	---	--	---

Comment :


1:500

Position

Code

Observation

Grade



STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
4	20	4.38	40	2	0	0	0	0	1


Inspection report / Inspection: 1


Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 11	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : C Pipe
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH06
Inspection Direction: MH06 (U/S) C Pipe	Pipe Length	D/S Depth :

Use: Surface water	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Vitrified clay
Total length : 0.60 m	Lining :

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH06	0
	0.00	WL	Water level, 0% of the vertical dimension	0
	0.50	DER	Settled deposits, coarse, 95% cross-sectional area loss	5
	0.60	SA	Survey abandoned Remarks: due to der	0



09:05:30 16-02-17 0.50m

LOCATION: LONDON
PLACE: DYNE HOUSE SCHOOL
JOB NO: 16/328
START MH: MH06
FINISH MH: C PIPE
SIZE: 100mm
MATERIAL: VC
USE: SURFACE

0.5 m

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	1	10	20	10	5

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
16/02/2017

Section number :
11

PLR Suffix :
X




Photo: 11_3A

0.5m, Settled deposits, coarse, 95% cross-sectional area loss

Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 12	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH10 (D/S) X Pipe	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH10 X Pipe
---	---	---	--	----------------------------------

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 1.56 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Vitrified clay
--	---	--	---

Comment :


1:500

Position

Code

Observation

Grade



	0.00	MH	Start node type, manhole, reference number : MH10	0
	0.00	WL	Water level, 5% of the vertical dimension	0
	1.56	DES	Settled deposits, fine, 10% cross-sectional area loss	3
	1.56	SA	Survey abandoned Remarks: due to des	0

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	1	2	1.28	2	3


Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 13	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH10 (D/S) X Pipe	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH10 X Pipe
---	---	---	--	----------------------------------

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 8.66 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Vitrified clay
--	---	--	---

Comment :

1:500	Position	Code	Observation	Grade
	MH10		Start node type, manhole, reference number : MH10	0
	0.00	MH		
	0.00	WL	Water level, 5% of the vertical dimension	0
	4.40	DES	Settled deposits, fine, 20% cross-sectional area loss	3
	5.40	DES	Settled deposits, fine, 15% cross-sectional area loss	3
	6.65 S01	DES	Settled deposits, fine, 10% cross-sectional area loss, Start3	
	6.76	WL	Water level, 10% of the vertical dimension	0
	7.71	WL	Water level, 50% of the vertical dimension	0
	8.66 F01	DES	Settled deposits, fine, 10% cross-sectional area loss, End 3	
	8.66	SA	Survey abandoned Remarks: due to wl	0



4.4 m

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
16/02/2017

Section number :
13

PLR Suffix :
X



Photo: 13_3A

4.4m, Settled deposits, fine, 20% cross-sectional area loss


Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 14	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : MH10
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : A Pipe
Inspection Direction: MH10 (D/S) A Pipe	Pipe Length	D/S Depth :

Use: Surface water	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Vitrified clay
Total length : 1.32 m	Lining :

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH10	0
	0.00	WL	Water level, 0% of the vertical dimension	0
	1.20	SC	Dimension changes, 25mm high, 25mm wide	0
	1.32	MHF	Finish node type, manhole reference number: A Pipe	0



1.2 m

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
16/02/2017

Section number :
14

PLR Suffix :
X



Photo: 14_3A

1.2m, Dimension changes, 25mm high, 25mm wide


Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 15	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH10 (U/S) B Pipe	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	B Pipe MH10
---	---	---	--	----------------------------------

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 11.02 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Vitrified clay
--	--	--	---

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH10	0
	0.50	WL	Water level, 10% of the vertical dimension	0
	3.22	JN	Junction, at 9 o'clock, diameter 100mm	0
	5.58	WL	Water level, 5% of the vertical dimension	0
	8.07	JDM	Joint displaced, medium	1
	10.79	JN	Junction, at 9 o'clock, diameter 100mm	0
	11.02	REM	General remark Remarks: node point	0
	11.02	MHF	Finish node type, manhole reference number: B Pipe	0



8.07 m

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
1	0	0	0	1	0	0	0	0	1

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
16/02/2017

Section number :
15

PLR Suffix :
X




Photo: 15_5A
8.07m, Joint displaced, medium

Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 16	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : MH07
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : Main
Inspection Direction: MH07 (D/S) Main	Pipe Length	D/S Depth :

Use: Combined	Pipe shape : Circular
Year laid : Z	Pipe size : 150 mm
Purpose : Routine inspection of condition	Pipe material : Vitrified clay
Total length : 3.10 m	Lining :

Comment : **Wrong finish and direction on recording**

1:500

Position

Code

Observation

Grade

	0.00	MH	Start node type, manhole, reference number : MH07	0
	0.00	WL	Water level, 5% of the vertical dimension	0
	0.80	LD	Line deviates down Remarks: critical	0
	1.44	WL	Water level, 20% of the vertical dimension	0
	2.27	WL	Water level, 5% of the vertical dimension	0
	3.10	REM	General remark Remarks: Finish Main	0
	3.10	MHF	Finish node type, manhole reference number: Main Remarks: Wrong finish on recording	0

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1

Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 17	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH13 (U/S) MH12	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH12 MH13
---	---	---	--	--

Use: Year laid : Purpose : Total length :	Foul Z Routine inspection of condition 11.26 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Cast iron
--	---	--	--

Comment :

1:500

Position

Code

Observation

Grade

MH13

0.00

MH

Start node type, manhole, reference number : MH13

0

0.00

WL

Water level, 5% of the vertical dimension

0

0.85

DES

Settled deposits, fine, 10% cross-sectional area loss

3

1.09

DES

Settled deposits, fine, 10% cross-sectional area loss

3

7.36

JN

Junction, at 9 o'clock, diameter 100mm

0

11.26

MHF

Finish node type, manhole reference number: MH12

0

MH12

0.85 m

STR no def

STR peak

STR mean

STR total

STR grade

SER no def

SER peak

SER mean

SER total

SER grade

0

0

0

0

1

2

2

0.36

4

3

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
16/02/2017

Section number :
17

PLR Suffix :
X



Photo: 17_3A

0.85m, Settled deposits, fine, 10% cross-sectional area loss


Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 18	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH12 (U/S) MH11	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH11 MH12
---	---	---	--	--

Use: Year laid : Purpose : Total length :	Foul Z Routine inspection of condition 6.37 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Cast iron
--	--	--	--

Comment :

1:500	Position	Code	Observation	Grade
				
	0.00	MH	Start node type, manhole, reference number : MH12	0
	0.00	WL	Water level, 10% of the vertical dimension	0
	3.31	JN	Junction, at 9 o'clock, diameter 100mm	0
	6.37	MHF	Finish node type, manhole reference number: MH11	0

Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 19	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : MH13
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH14
Inspection Direction: MH13 (D/S) MH14	Pipe Length	D/S Depth :

Use: Foul	Pipe shape : Circular
Year laid : Z	Pipe size : 150 mm
Purpose : Routine inspection of condition	Pipe material : Cast iron
Total length : 8.07 m	Lining :

Comment :

1:500

Position

Code

Observation

Grade

Diagram illustrating a sewer inspection with two manholes, MH13 and MH14, connected by a vertical pipe. The diagram shows the following data points:

- 0.00: MH13 (Start node type, manhole, reference number : MH13)
- 0.00: WL (Water level, 5% of the vertical dimension)
- 3.22: DEX (Settled deposits, other, 10% cross-sectional area loss. Remarks: Rags)
- 5.58: WL (Water level, 10% of the vertical dimension)
- 6.88: DEX (Settled deposits, other, 25% cross-sectional area loss. Remarks: rags)
- 8.07: MHF (Finish node type, manhole reference number: MH14)

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	2	5	0.87	7	4


Inspection report / Inspection: 1

Date : 16/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 20	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH14 (D/S) MH15	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH14 MH15
---	---	---	--	--

Use: Year laid : Purpose : Total length :	Foul Z Routine inspection of condition 3.22 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 150 mm Cast iron
--	--	--	--

Comment :

1:500	Position	Code	Observation	Grade
				
	0.00	MH	Start node type, manhole, reference number : MH14	0
	0.00	WL	Water level, 5% of the vertical dimension	0
	0.30	LD	Line deviates down Remarks: critical	0
	1.30	LD	Line deviates down Remarks: critical	0
	2.30	LD	Line deviates down Remarks: critical	0
	3.22	SA	Survey abandoned Remarks: due to bends	0

Inspection report / Inspection: 1


Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 22	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : Sinks
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH11
Inspection Direction: MH11 (U/S) Sinks	Pipe Length	D/S Depth :

Use: Foul	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Cast iron
Total length : 2.86 m	Lining :

Comment :

1:500 Position Code Observation Grade



STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
17/02/2017

Section number :
22

PLR Suffix :
X



Photo: 22_4A

2.86m, Finish node type, manhole reference number: Sinks

Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 23	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : B Pipe
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH11
Inspection Direction: MH11 (U/S) B Pipe	Pipe Length	D/S Depth :

Use: Foul	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Cast iron
Total length : 0.50 m	Lining :

Comment :

1:500

Position

Code

Observation

Grade

MH11

0.00

0.00

0.50

0.50

MH

Start node type, manhole, reference number : MH11

0

WL

Water level, 10% of the vertical dimension

0

DEX

Settled deposits, other, 50% cross-sectional area loss
Remarks: rags

4

SA

Survey abandoned Remarks: due to dex 50%

0

09:12:15

17-02-17

0.50m

LOCATION: LONDON

PLACE: DYNE HOUSE SCHOOL

JOB NO: 16/328

START MH: MH11

FINISH MH: B PIPE

SIZE: 100mm

MATERIAL: CI

USE: FOUL

0.5 m

STR no def

STR peak

STR mean

STR total

STR grade

SER no def

SER peak

SER mean

SER total

SER grade

0

0

0

0

1

1

8

16

8

5

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
17/02/2017

Section number :
23

PLR Suffix :
X




Photo: 23_3A

0.5m, Settled deposits, other, 50% cross-sectional area loss

Remarks: rags


Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 24	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : C Pipe
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH11
Inspection Direction: MH11 (U/S) C Pipe	Pipe Length	D/S Depth :

Use: Foul	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Cast iron
Total length : 0.73 m	Lining :

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH11	0
	0.00	WL	Water level, 5% of the vertical dimension	0
	0.50	DEX	Settled deposits, other, 20% cross-sectional area loss Remarks: rags	4
	0.73	SA	Survey abandoned Remarks: due to dex	0



Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
17/02/2017

Section number :
24

PLR Suffix :
X




Photo: 24_3A

0.5m, Settled deposits, other, 20% cross-sectional area loss

Remarks: rags


Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 25	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH11 (U/S) WC	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	WC MH11
---	---	---	--	--------------------------------------

Use: Year laid : Purpose : Total length :	Foul Z Routine inspection of condition 1.56 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Cast iron
--	--	--	--

Comment :

1:500	Position	Code	Observation	Grade
				
		MH	Start node type, manhole, reference number : MH11	0
		WL	Water level, 5% of the vertical dimension	0
		LL	Line deviates left Remarks: Marginal	0
		LU	Line deviates up Remarks: critical	0
		MHF	Finish node type, manhole reference number: WC	0

Inspection report / Inspection: 1


Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 26	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : E Pipe
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH11
Inspection Direction: MH11 (U/S) E Pipe	Pipe Length	D/S Depth :

Use: Foul	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Cast iron
Total length : 3.10 m	Lining :

Comment :

1:500 Position Code Observation Grade



STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1


Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 27	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH11 (U/S) F Pipe	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	F Pipe MH11
---	---	---	--	----------------------------------

Use: Year laid : Purpose : Total length :	Foul Z Routine inspection of condition 5.23 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Cast iron
--	--	--	--

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH11	0
	0.00	WL	Water level, 5% of the vertical dimension	0
	0.50	LL	Line deviates left Remarks: marginal	0
	0.60	DES	Settled deposits, fine, 25% cross-sectional area loss	4
	1.68	DES	Settled deposits, fine, 15% cross-sectional area loss	3
	2.74	DES	Settled deposits, fine, 25% cross-sectional area loss	4
	3.81	DES	Settled deposits, fine, 35% cross-sectional area loss	4
	4.63	DES	Settled deposits, fine, 50% cross-sectional area loss	4
	5.23	SA	Survey abandoned Remarks: due to des	0



2.74 m



4.63 m

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	5	5	4.4	22	4

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
17/02/2017

Section number :
27

PLR Suffix :
X




Photo: 27_6A

2.74m, Settled deposits, fine, 25% cross-sectional area loss




Photo: 27_8A

4.63m, Settled deposits, fine, 50% cross-sectional area loss


Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 28	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : G Pipe
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH11
Inspection Direction: MH11 (U/S) G Pipe	Pipe Length	D/S Depth :

Use: Foul	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Cast iron
Total length : 0.61 m	Lining :

Comment :

1:500	Position	Code	Observation	Grade
	MH11	MH	Start node type, manhole, reference number : MH11	0
	0.00	WL	Water level, 5% of the vertical dimension	0
	0.50	DES	Settled deposits, fine, 20% cross-sectional area loss	3
	0.61	DEE	Attached deposits, encrustation, from 7 to 5 o'clock, 30% cross-sectional area loss Remarks: scale	4
	0.61	SA	Survey abandoned Remarks: due to dee	0



STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	2	5	11.48	7	5

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
17/02/2017

Section number :
28

PLR Suffix :
X



Photo: 28_3A

0.5m, Settled deposits, fine, 20% cross-sectional area loss




Photo: 28_4A

0.61m, Attached deposits, encrustation, from 7 to 5 o'clock, 30% cross-sectional area loss
Remarks: scale

Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 29	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) Rodding Ey (D/S) MH12	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	Rodding Ey MH12
---	---	---	--	--------------------------------------

Use: Year laid : Purpose : Total length :	Foul Z Routine inspection of condition 2.39 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 100 mm Cast iron
--	--	--	--

Comment :


1:500

Position

Code

Observation

Grade



	0.00	MH	Start node type, manhole, reference number : Rodding Ey 0	
	0.00	WL	Water level, 0% of the vertical dimension	0
	0.00	LD	Line deviates down Remarks: critical	0
	1.80	LL	Line deviates left Remarks: slight	0
	2.39	MHF	Finish node type, manhole reference number: MH12	0

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1


Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 30	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH16 (U/S) MH15	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH15 MH16
---	---	---	--	--

Use: Year laid : Purpose : Total length :	Foul Z Routine inspection of condition 14.22 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 150 mm Cast iron
--	---	--	--

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH16	0
	0.00	WL	Water level, 5% of the vertical dimension	0
	1.68	DEX	Settled deposits, other, 30% cross-sectional area loss Remarks: rags	4
	2.00	WL	Water level, 25% of the vertical dimension	0
	6.65	WL	Water level, 10% of the vertical dimension	0
	13.74	LR	Line deviates right Remarks: marginal	0
	14.22	MHF	Finish node type, manhole reference number: MH15	0



Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
17/02/2017

Section number :
30

PLR Suffix :
X



Photo: 30_3A

1.68m, Settled deposits, other, 30% cross-sectional area loss

Remarks: rags


Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 32	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH16 (D/S) Main	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	MH16 Main
---	---	---	--	--------------------------------

Use: Year laid : Purpose : Total length :	Foul Z Routine inspection of condition 2.62 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 150 mm Vitrified clay
--	--	--	---

Comment :

1:500	Position	Code	Observation	Grade
				
	0.00	MH	Start node type, manhole, reference number : MH16	0
	0.00	WL	Water level, 0% of the vertical dimension	0
	0.50	LD	Line deviates down Remarks: critical	0
	2.27	LR	Line deviates right Remarks: slight	0
	2.62	MHF	Finish node type, manhole reference number: Main	0

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	0	0	0	0	1

Inspection report / Inspection: 1



Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 33	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : MH17
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH16
Inspection Direction: MH16 (U/S) MH17	Pipe Length	D/S Depth :

Use: Foul	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Vitrified clay
Total length : 14.22 m	Lining :

Comment :

1:500 Position Code Observation Grade



STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
1	0	0	0	1	0	0	0	0	1

Inspection pictures / Inspection: 1

Place :
London

Road :
Highgate School, Dyne House

Date :
17/02/2017

Section number :
33

PLR Suffix :
X



Photo: 33_3A

3.82m, Cracks, multiple at joint, from 7 to 5 o'clock


Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 34	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : London	Location details:	U/S MH : Gully
Road : Highgate School, Dyne House	Catchment:	U/S Depth :
Location Other (state in comments)	Tape number :	D/S MH : MH17
Inspection Direction: MH17 (U/S) Gully	Pipe Length	D/S Depth :

Use: Surface water	Pipe shape : Circular
Year laid : Z	Pipe size : 100 mm
Purpose : Routine inspection of condition	Pipe material : Vitrified clay
Total length : 6.41 m	Lining :

Comment :

1:500	Position	Code	Observation	Grade
	0.00	MH	Start node type, manhole, reference number : MH17	0
	0.00	WL	Water level, 0% of the vertical dimension	0
	0.85	LL	Line deviates left Remarks: critical	0
	2.39	MC	Material changes, cast iron	0
	6.41	LD	Line deviates down Remarks: critical	0
	6.41	MHF	Finish node type, manhole reference number: Gully	0


Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 35	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH06 (U/S) D Pipe	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	D Pipe MH06
---	---	---	--	----------------------------------

Use: Year laid : Purpose : Total length :	Other (state in comments) Z Routine inspection of condition 2.15 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 150 mm Vitrified clay
--	---	--	---

Comment : **use is unknown**

1:500	Position	Code	Observation	Grade					
									
	0.00	MH	Start node type, manhole, reference number : MH06	0					
	0.00	WL	Water level, 0% of the vertical dimension	0					
	0.60	DER	Settled deposits, coarse, 10% cross-sectional area loss	3					
	1.56	DER	Settled deposits, coarse, 10% cross-sectional area loss	3					
	1.56	CC	Crack, circumferential, from 9 to 12 o'clock	2					
	1.56	LU	Line deviates up Remarks: critical	0					
	2.15	MHF	Finish node type, manhole reference number: D Pipe	0					
STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
1	10	4.65	10	2	2	2	1.86	4	3

Inspection report / Inspection: 1

Date : 17/02/2017	Job number :	Weather : no rain or snow	Operator : NA	Section number : 36	PLR SUFFIX: X
Weather no rain or snow	Vehicle :	Camera : Push Rod	Preset :	Cleaned : not known	Operator : NA

Place : Road : Location Inspection Direction	London Highgate School, Dyne House Other (state in comments) MH07 (U/S) B Pipe	Location details: Catchment: Tape number : Pipe Length	U/S MH : U/S Depth : D/S MH : D/S Depth :	B Pipe MH07
---	---	---	--	----------------------------------

Use: Year laid : Purpose : Total length :	Surface water Z Routine inspection of condition 17.87 m	Pipe shape : Pipe size : Pipe material : Lining :	Circular 150 mm Vitrified clay
--	--	--	---

Comment :

1:500

Position

Code

Observation

Grade

	0.00	MH	Start node type, manhole, reference number : MH07	0
	0.00	WL	Water level, 20% of the vertical dimension	0
	0.00	WL	Water level, 5% of the vertical dimension	0
	0.50	DES	Settled deposits, fine, 10% cross-sectional area loss	3
	16.80	MC	Material changes, cast iron	0
	16.82	JN	Junction, at 12 o'clock, diameter 100mm	0
	17.87	MHF	Finish node type, manhole reference number: B Pipe	0

STR no def	STR peak	STR mean	STR total	STR grade	SER no def	SER peak	SER mean	SER total	SER grade
0	0	0	0	1	1	2	0.11	2	3

ΣØ / Main sections / Inspection: 1

Project name : Highgate School, Dyne House, South	Project number : 16/328	Contact : Anna Collins	Date : 24/02/2017
---	-----------------------------------	----------------------------------	-----------------------------

Nr.	US MH	DS MH	Date	Road	Tape No.	Material	m	(m)
1	MH01	MH02	15/01/2017	Highgate School, Dyne House		Vitrified clay	15.50	15.50
5	RWP01	MH03	15/02/2017	Highgate School, Dyne House		Vitrified clay	4.00	4.00
6	Gully	MH03	15/02/2017	Highgate School, Dyne House		Vitrified clay	26.20	26.20
7	MH05	MH06	15/02/2017	Highgate School, Dyne House		Vitrified clay	15.10	15.10
9	MH08	MH06	15/02/2017	Highgate School, Dyne House		Vitrified clay	23.31	23.31
11	C Pipe	MH06	16/02/2017	Highgate School, Dyne House		Vitrified clay	0.60	0.60
12	MH10	X Pipe	16/02/2017	Highgate School, Dyne House		Vitrified clay	1.56	1.56
13	MH10	X Pipe	16/02/2017	Highgate School, Dyne House		Vitrified clay	8.66	8.66
14	MH10	A Pipe	16/02/2017	Highgate School, Dyne House		Vitrified clay	1.32	1.32
15	B Pipe	MH10	16/02/2017	Highgate School, Dyne House		Vitrified clay	11.02	11.02
17	MH12	MH13	16/02/2017	Highgate School, Dyne House		Cast iron	11.26	11.26
18	MH11	MH12	16/02/2017	Highgate School, Dyne House		Cast iron	6.37	6.37
22	Sinks	MH11	17/02/2017	Highgate School, Dyne House		Cast iron	2.86	2.86
23	B Pipe	MH11	17/02/2017	Highgate School, Dyne House		Cast iron	0.50	0.50
24	C Pipe	MH11	17/02/2017	Highgate School, Dyne House		Cast iron	0.73	0.73
25	WC	MH11	17/02/2017	Highgate School, Dyne House		Cast iron	1.56	1.56
26	E Pipe	MH11	17/02/2017	Highgate School, Dyne House		Cast iron	3.10	3.10
27	F Pipe	MH11	17/02/2017	Highgate School, Dyne House		Cast iron	5.23	5.23
28	G Pipe	MH11	17/02/2017	Highgate School, Dyne House		Cast iron	0.61	0.61
29	Rodding Ey	MH12	17/02/2017	Highgate School, Dyne House		Cast iron	2.39	2.39
33	MH17	MH16	17/02/2017	Highgate School, Dyne House		Vitrified clay	14.22	14.22
34	Gully	MH17	17/02/2017	Highgate School, Dyne House		Vitrified clay	6.41	6.41

Pipe size: CIRCULAR 100 = 162.51 m (162.51 m)

Nr.	US MH	DS MH	Date	Road	Tape No.	Material	m	(m)
2	MH02	MH03	15/02/2017	Highgate School, Dyne House		Vitrified clay	8.70	8.70
3	A Pipe	MH02	15/02/2017	Highgate School, Dyne House		Vitrified clay	6.60	6.60
4	MH03	MH04	15/02/2017	Highgate School, Dyne House		Vitrified clay	25.90	25.90
8	MH04	MH07	15/02/2017	Highgate School, Dyne House		Vitrified clay	17.40	17.40
10	MH06	MH09	15/02/2017	Highgate School, Dyne House		Vitrified clay	9.13	9.13
16	MH07	Main	16/02/2017	Highgate School, Dyne House		Vitrified clay	3.10	3.10
19	MH13	MH14	16/02/2017	Highgate School, Dyne House		Cast iron	8.07	8.07
20	MH14	MH15	16/02/2017	Highgate School, Dyne House		Cast iron	3.22	3.22
21	DP01	MH13	16/02/2017	Highgate School, Dyne House		Cast iron	2.39	2.39
30	MH15	MH16	17/02/2017	Highgate School, Dyne House		Cast iron	14.22	14.22
31	MH14	MH15	17/02/2017	Highgate School, Dyne House		Cast iron	2.74	2.74
32	MH16	Main	17/02/2017	Highgate School, Dyne House		Vitrified clay	2.62	2.62
35	D Pipe	MH06	17/02/2017	Highgate School, Dyne House		Vitrified clay	2.15	2.15
36	B Pipe	MH07	17/02/2017	Highgate School, Dyne House		Vitrified clay	17.87	17.87

Pipe size: CIRCULAR 150 = 124.11 m (124.11 m)

All sections = 286.62 m (286.62 m)

Service / Operational Defects (SRM 4) / Inspection: 1

Project name : Highgate School, Dyne House, South	Project Number : 16/328	Contact : Anna Collins	Date : 24/02/2017
--	----------------------------	---------------------------	----------------------

No.	PLR	Dir.	Use	Shape / Size	Date	Mat.	Total Length	Insp. Length	Peak HWG	Peak Score	Grade	Mean Score	Total Score
1	MH01X	D	C	C 100	15/01/2017	VC	15.50	15.50	3	4	3	2.28	35.4
2	MH02X	U	C	C 150	15/02/2017	VC	8.70	8.70	2	2	3	1.89	16.4
3	A PipeX	U	C	C 150	15/02/2017	VC	6.60	6.60	2	0	1	0	0
4	MH03X	D	C	C 150	15/02/2017	VC	25.90	25.90	1	3	3	2.04	52.8
5	RWP01X	U	S	C 100	15/02/2017	VC	4.00	4.00	3	1	2	0.88	3.5
6	GullyX	U	S	C 100	15/02/2017	VC	26.20	26.20	3				
7	MH05X	D	S	C 100	15/02/2017	VC	15.10	15.10	2	0	1	0	0
8	MH04X	D	C	C 150	15/02/2017	VC	17.40	17.40	3	7	4	2.23	38.8
9	MH08X	D	S	C 100	15/02/2017	VC	23.31	23.31	3	8	4	0.86	20
10	MH06X	D	S	C 150	15/02/2017	VC	9.13	9.13	-	0	1	0	0
11	C PipeX	U	S	C 100	16/02/2017	VC	0.60	0.60	3	10	5	20	10
12	MH10X	D	S	C 100	16/02/2017	VC	1.56	1.56	3	2	3	1.28	2
13	MH10X	D	S	C 100	16/02/2017	VC	8.66	8.66	3	4	3	0.92	8
14	MH10X	D	S	C 100	16/02/2017	VC	1.32	1.32	-	0	1	0	0
15	B PipeX	U	S	C 100	16/02/2017	VC	11.02	11.02	-	0	1	0	0
16	MH07X	D	C	C 150	16/02/2017	VC	3.10	3.10	-	0	1	0	0
17	MH12X	U	F	C 100	16/02/2017	CI	11.26	11.26	3	2	3	0.36	4
18	MH11X	U	F	C 100	16/02/2017	CI	6.37	6.37	-	0	1	0	0
19	MH13X	D	F	C 150	16/02/2017	CI	8.07	8.07	-	5	4	0.87	7
20	MH14X	D	F	C 150	16/02/2017	CI	3.22	3.22	-	0	1	0	0
21	DP01X	U	F	C 150	16/02/2017	CI	2.39	2.39	-	0	1	0	0
22	SinksX	U	F	C 100	17/02/2017	CI	2.86	2.86	-	0	1	0	0
23	B PipeX	U	F	C 100	17/02/2017	CI	0.50	0.50	-	8	5	16	8
24	C PipeX	U	F	C 100	17/02/2017	CI	0.73	0.73	-	5	5	10	5
25	WCX	U	F	C 100	17/02/2017	CI	1.56	1.56	3	0	1	0	0
26	E PipeX	U	F	C 100	17/02/2017	CI	3.10	3.10	-	0	1	0	0
27	F PipeX	U	F	C 100	17/02/2017	CI	5.23	5.23	3	5	4	4.4	22
28	G PipeX	U	F	C 100	17/02/2017	CI	0.61	0.61	3	5	5	11.48	7
29	Rodding EyX	D	F	C 100	17/02/2017	CI	2.39	2.39	3	0	1	0	0
30	MH15X	U	F	C 150	17/02/2017	CI	14.22	14.22	-	5	4	0.35	5
31	MH14X	U	F	C 150	17/02/2017	CI	2.74	2.74	-	0	1	0	0
32	MH16X	D	F	C 150	17/02/2017	VC	2.62	2.62	-	0	1	0	0
33	MH17X	U	F	C 100	17/02/2017	VC	14.22	14.22	-	0	1	0	0
34	GullyX	U	S	C 100	17/02/2017	VC	6.41	6.41	3	0	1	0	0
35	D PipeX	U	Z	C 150	17/02/2017	VC	2.15	2.15	3	2	3	1.86	4
36	B PipeX	U	S	C 150	17/02/2017	VC	17.87	17.87	3	2	3	0.11	2

Structural Defects (SRM 4) / Inspection: 1

Project name : Highgate School, Dyne House, South	Project Number : 16/328	Contact : Anna Collins	Date : 24/02/2017
--	----------------------------	---------------------------	----------------------

No.	PLR	Dir.	Use	Shape / Size	Date	Mat.	Total Length	Insp. Length	Peak HWG	Peak Score	Grade	Mean Score	Total Score
1	MH01X	D	C	C 100	15/01/2017	VC	15.50	15.50	2	0	1	0	0
2	MH02X	U	C	C 150	15/02/2017	VC	8.70	8.70	3	0	1	0	0
3	A PipeX	U	C	C 150	15/02/2017	VC	6.60	6.60	-	0	1	0	0
4	MH03X	D	C	C 150	15/02/2017	VC	25.90	25.90	3	80	4	6.56	170
5	RWP01X	U	S	C 100	15/02/2017	VC	4.00	4.00	-	0	1	0	0
6	GullyX	U	S	C 100	15/02/2017	VC	26.20	26.20	-				
7	MH05X	D	S	C 100	15/02/2017	VC	15.10	15.10	3	0	1	0	0
8	MH04X	D	C	C 150	15/02/2017	VC	17.40	17.40	4	80	4	10.34	180
9	MH08X	D	S	C 100	15/02/2017	VC	23.31	23.31	3	40	3	1.72	40
10	MH06X	D	S	C 150	15/02/2017	VC	9.13	9.13	2	20	2	4.38	40
11	C PipeX	U	S	C 100	16/02/2017	VC	0.60	0.60	-	0	1	0	0
12	MH10X	D	S	C 100	16/02/2017	VC	1.56	1.56	-	0	1	0	0
13	MH10X	D	S	C 100	16/02/2017	VC	8.66	8.66	-	0	1	0	0
14	MH10X	D	S	C 100	16/02/2017	VC	1.32	1.32	-	0	1	0	0
15	B PipeX	U	S	C 100	16/02/2017	VC	11.02	11.02	1	0	1	0	0
16	MH07X	D	C	C 150	16/02/2017	VC	3.10	3.10	-	0	1	0	0
17	MH12X	U	F	C 100	16/02/2017	CI	11.26	11.26	-	0	1	0	0
18	MH11X	U	F	C 100	16/02/2017	CI	6.37	6.37	-	0	1	0	0
19	MH13X	D	F	C 150	16/02/2017	CI	8.07	8.07	-	0	1	0	0
20	MH14X	D	F	C 150	16/02/2017	CI	3.22	3.22	-	0	1	0	0
21	DP01X	U	F	C 150	16/02/2017	CI	2.39	2.39	-	0	1	0	0
22	SinksX	U	F	C 100	17/02/2017	CI	2.86	2.86	-	0	1	0	0
23	B PipeX	U	F	C 100	17/02/2017	CI	0.50	0.50	-	0	1	0	0
24	C PipeX	U	F	C 100	17/02/2017	CI	0.73	0.73	-	0	1	0	0
25	WCX	U	F	C 100	17/02/2017	CI	1.56	1.56	-	0	1	0	0
26	E PipeX	U	F	C 100	17/02/2017	CI	3.10	3.10	-	0	1	0	0
27	F PipeX	U	F	C 100	17/02/2017	CI	5.23	5.23	-	0	1	0	0
28	G PipeX	U	F	C 100	17/02/2017	CI	0.61	0.61	-	0	1	0	0
29	Rodding EyX	D	F	C 100	17/02/2017	CI	2.39	2.39	-	0	1	0	0
30	MH15X	U	F	C 150	17/02/2017	CI	14.22	14.22	-	0	1	0	0
31	MH14X	U	F	C 150	17/02/2017	CI	2.74	2.74	-	0	1	0	0
32	MH16X	D	F	C 150	17/02/2017	VC	2.62	2.62	-	0	1	0	0
33	MH17X	U	F	C 100	17/02/2017	VC	14.22	14.22	3	0	1	0	0
34	GullyX	U	S	C 100	17/02/2017	VC	6.41	6.41	-	0	1	0	0
35	D PipeX	U	Z	C 150	17/02/2017	VC	2.15	2.15	2	10	2	4.65	10
36	B PipeX	U	S	C 150	17/02/2017	VC	17.87	17.87	-	0	1	0	0

Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH01

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z

Status: PR

Function: CO

Node Type: MH

Survey Date: 15/02/17

Manufacturer:

Grating:

COVER

Shape: R

Hinged:

Lockable:

Duty: M

Size: 670x500

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth:

Size:

Vermin:

CHAMBER

Soffit Type:

No. of Step Irons:

No. of Ladders:

No. of Landings:

Size: 590x450

Const'n Code: BR

Depth of Flow:

Depth of Silt:


H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	A Pipe	C	100		VC		0.57	
	B	B Pipe	C	100		PVC		0.40	
	C	C Pipe	C	100		VC		0.38	
	D								
	E								
	F								
OUTGOING PIPES	X	MH02	C	100		VC		0.60	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks:



Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH02

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid:

Status:

Function:

Node Type: MH

Survey Date: 15/02/17

Manufacturer:

Grating:

COVER

Shape:

Hinged:

Lockable:

Duty:

Size:

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth:

Size:

Vermin:

CHAMBER

Soffit Type:

No. of Step Irons:

No. of Ladders:

No. of Landings:

Size:

Const'n Code:

Depth of Flow:

Depth of Silt:

H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size			Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A										
	B										
	C										
	D										
	E										
	F										
OUTGOING PIPES	X										
	Y										

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover		Irons/Ladders		Shaft		Chamber		Benching		Other	
-------	--	---------------	--	-------	--	---------	--	----------	--	-------	--

Remarks: Unable to locate

--	--

Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH03

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z

Status: PR

Function: CO

Node Type: MH

Survey Date: 15/02/17

Manufacturer:

Grating:

COVER

Shape: R

Hinged:

Lockable:

Duty: M

Size: 660x550

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses: 3

Depth: 460

Size: 630x480

Vermin:

CHAMBER

Soffit Type: S

No. of Step Irons: 1

No. of Ladders:

No. of Landings:

Size: 930x680

Const'n Code: BR

Depth of Flow: 10mm

Depth of Silt:

H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size		Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	MH02	C	150			VC		1.63	
	B	RWP01	C	100			VC		1.58	
	C	GULLY	C	100			VC		1.58	
	D									
	E									
	F									
OUTGOING PIPES	X	MH04	C	150			VC		1.70	
	Y									

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks:



Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH04

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z

Status: PR

Function: CO

Node Type: MH

Survey Date: 16/02/17

Manufacturer:

Grating:

COVER

Shape: S

Hinged:

Lockable:

Duty: H

Size: 920Ø

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth:

Size:

Vermin:

CHAMBER

Soffit Type:

No. of Step Irons: 4

No. of Ladders:

No. of Landings:

Size: 590x470

Const'n Code: BR

Depth of Flow: 5mm

Depth of Silt:


H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	MH03	C	150		VC		4.18	
	B	B Pipe	C	100		VC		5.40	
	C								
	D								
	E								
	F								
OUTGOING PIPES	X	MH07	C	150		VC		4.30	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks: Slab used as a cover



Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH05

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z

Status: PR

Function: SW

Node Type: MH

Survey Date: 15/02/17

Manufacturer:

Grating:

COVER

Shape: R

Hinged:

Lockable:

Duty: M

Size: 640x490

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses: 1

Depth: 160

Size: 620x480

Vermin:

CHAMBER

Soffit Type: S

No. of Step Irons: 3

No. of Ladders:

No. of Landings:

Size: 1120x930

Const'n Code: CO

Depth of Flow:

Depth of Silt: 10mm


H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	A Pipe	C	100		VC		3.03	
	B	B Pipe	C	100		VC		0.84	
	C	C Pipe	C	100		VC		3.00	
	D	D Pipe	C	100		VC		3.00	
	E	E Pipe	C	100		VC		3.00	
	F	F Pipe	C	100		VC		1.30	
OUTGOING PIPES	X	MH06	C	100		VC		3.10	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks:



Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH06

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z

Status: PR

Function: SW

Node Type: MH

Survey Date: 15/02/17

Manufacturer:

Grating:

COVER

Shape: R

Hinged:

Lockable:

Duty: M

Size: 680x540

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth:

Size:

Vermin:

CHAMBER

Soffit Type:

No. of Step Irons: 3

No. of Ladders:

No. of Landings:

Size: 630x440

Const'n Code: BR

Depth of Flow:

Depth of Silt:


H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size		Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	MH08	C	100			VC		2.90	
	B	MH06	C	100			VC		2.80	
	C	C Pipe	C	100			VC		2.30	
	D									
	E									
	F									
OUTGOING PIPES	X	MH07	C	100			VC		3.00	
	Y									

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks:



Job Number: 16/328 Survey By: NA

Grid Ref: Node Number: MH07 Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z Status: PR Function: CO Node Type: MH Survey Date: 15/02/17

Manufacturer: Grating:

COVER Shape: R Hinged: Lockable: Duty: M Size: 620x540 Toxic atmos:

SHAFT Side Entry: Regulating Courses: Depth: Size: Vermin:

CHAMBER Soffit Type: No. of Step Irons: 1 No. of Ladders: No. of Landings:


Size: 680x520 Const'n Code: BR Depth of Flow: 10mm Depth of Silt: 20mm H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size			Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	MH08	C	150				VC		1.44	
	B	Valve Chamber	C	100				VC		1.39	
	C	MH06	C	100				VC		1.29	
	D	D Pipe	C	150				VC		1.15	
	E										
	F										
OUTGOING PIPES	X	Main	C	150				VC		1.50	
	Y										

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks: P Trap for X Pipe



Job Number: 16/328 Survey By: NA

Grid Ref: Node Number: MH08 Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z Status: PR Function: SW Node Type: MH Survey Date: 15/02/17

Manufacturer: Grating:

COVER Shape: R Hinged: Lockable: Duty: M Size: 670x540 Toxic atmos:

SHAFT Side Entry: Regulating Courses: Depth: 250 Size: 620x460 Vermin:

CHAMBER Soffit Type: No. of Step Irons: 2 No. of Ladders: No. of Landings:


Size: 940x530 Const'n Code: BR Depth of Flow: Depth of Silt: 80mm H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size			Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	A Pipe	C	100				VC		0.82	
	B	B Pipe	C	100				VC		0.74	
	C										
	D										
	E										
	F										
OUTGOING PIPES	X	MH08	C	100				VC		0.83	
	Y										

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks: Soffit type is tapered.



Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH09

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid:

Status:

Function:

Node Type: MH

Survey Date: 15/02/17

Manufacturer:

Grating:

COVER

Shape:

Hinged:

Lockable:

Duty:

Size:

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth:

Size:

Vermin:

CHAMBER

Soffit Type:

No. of Step Irons:

No. of Ladders:

No. of Landings:

Size:

Const'n Code:

Depth of Flow:

Depth of Silt:

H of S:

Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
------	------------------------	-------	-----------	-------------------	---------------	-----------------	----------------------	------------------

INCOMING PIPES	A							
	B							
	C							
	D							
	E							
	F							

OUTGOING PIPES	X							
	Y							

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover		Irons/Ladders		Shaft		Chamber		Benching		Other	
-------	--	---------------	--	-------	--	---------	--	----------	--	-------	--

Remarks: Manhole 9 doesn't exist

--	--

Job Number: 16/328 Survey By: NA

Grid Ref: Node Number: MH10 Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z Status: PR Function:SW Node Type: MH Survey Date: 15/02/17

Manufacturer: Grating:

COVER Shape: R Hinged: Lockable: Duty: M Size:640x520 Toxic atmos:

SHAFT Side Entry: Regulating Courses: Depth: 260 Size:620x480 Vermin:

CHAMBER Soffit Type:BR No. of Step Irons: No. of Ladders: No. of Landings:


Size:680x650 Const'n Code:BR Depth of Flow: Depth of Silt: H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	A Pipe	C	100		VC		0.87	
	B	B Pipe	C	100		VC		0.83	
	C								
	D								
	E								
	F								
OUTGOING PIPES	X	X Pipe	C	100		VC		0.85	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks: X Pipe assumed into MH06



Job Number: 16/328 Survey By: NA

Grid Ref: Node Number: MH11 Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z Status: PR Function:FW Node Type: MH Survey Date: 15/02/17

Manufacturer: Grating:

COVER Shape: R Hinged: Lockable: Duty: M Size:670x520 Toxic atmos:

SHAFT Side Entry: Regulating Courses: Depth: 280 Size:670x420 Vermin:

CHAMBER Soffit Type:S No. of Step Irons: 1 No. of Ladders: No. of Landings:


Size:1430x840 Const'n Code:BR Depth of Flow: 10mm Depth of Silt:10mm H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	Sink	C	100		CI		1.55	
	B	B Pipe	C	100		CI		1.45	
	C	C Pipe	C	100		CI		1.45	
	D	Toilets	C	100		CI		1.45	
	E	E Pipe	C	100		CI		1.45	
	F	F Pipe	C	100		CI		1.45	
	G	G Pipe	C	100		CI		1.45	
OUTGOING PIPES	X	MH12	C	100		CI		1.60	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks: Cover over invert, no bolts



Job Number: 16/328 Survey By: NA

Grid Ref: Node Number: MH13 Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z Status: PR Function:FW Node Type: MH Survey Date: 15/02/17

Manufacturer: Grating:

COVER Shape: R Hinged: Lockable: Duty: M Size:680x530 Toxic atmos:

SHAFT Side Entry: Regulating Courses: Depth: 360 Size:620x470 Vermin:

CHAMBER Soffit Type:S No. of Step Irons: 3 No. of Ladders: No. of Landings:

Size:1360x1300 Const'n Code:BR Depth of Flow: 10mm Depth of Silt:5mm H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	DP01	C	150		CI		2.40	
	B	DP02	C	100		CI		2.30	
	C	MH12	C	100		CI		2.30	
	D	DP03	C	100		CI		2.30	
	E								
	F								
OUTGOING PIPES	X	MH14	C	150		CI		2.45	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks: Cast iron invert, Has a cast iron lid, nuts and bolts possibly need replacing.
2 x CI external pipes into chamber.



Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH14

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z

Status: PR

Function:FW

Node Type: MH

Survey Date: 17/02/17

Manufacturer:

Grating:

COVER

Shape: R

Hinged:

Lockable:

Duty: M

Size:680x520

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth: 220

Size:600x450

Vermin:

CHAMBER

Soffit Type:S

No. of Step Irons: 3

No. of Ladders:

No. of Landings:

Size:1380x930

Const'n Code:BR

Depth of Flow: 20mm

Depth of Silt:5mm


H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size			Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	MH13		C	150			CI		2.18	
	B	B Pipe		C	100			CI		2.10	
	C	C Pipe		C	100			CI		2.10	
	D	D Pipe		C	100			CI		2.10	
	E	E Pipe		C	100			CI		2.10	
	F										
OUTGOING PIPES	X	MH15		C	150			CI		2.20	
	Y										

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks:



Job Number: 16/328 Survey By: NA

Grid Ref: Node Number: MH16 Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z Status: PR Function:FW Node Type: MH Survey Date: 17/02/17

Manufacturer: Grating:

COVER Shape: R Hinged: Lockable: Duty: M Size:680x520 Toxic atmos:

SHAFT Side Entry: Regulating Courses:1 Depth: 240 Size:620x460 Vermin:

CHAMBER Soffit Type:S No. of Step Irons: 2 No. of Ladders: No. of Landings:


Size:880x820 Const'n Code:BR Depth of Flow: 20mm Depth of Silt: H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	MH15	C	150		CI		0.79	
	B	B Pipe	C	100		VC		0.65	
	C	MH17	C	100		VC		0.65	
	D	D Pipe	C	100		VC		0.65	
	E	E Pipe	C	100		VC		0.65	
	F								
OUTGOING PIPES	X	Main	C	150		CI		0.80	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks: 2 External cast iron pipes from the heating system.



Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: MH17

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z

Status: PR

Function: SW

Node Type: MH

Survey Date: 17/02/17

Manufacturer:

Grating:

COVER

Shape: R

Hinged:

Lockable:

Duty: M

Size: 750x600

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth:

Size:

Vermin:

CHAMBER

Soffit Type:

No. of Step Irons:

No. of Ladders:

No. of Landings:

Size: 620x470

Const'n Code: BR

Depth of Flow:

Depth of Silt:


H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A	Gully	C	100		VC		0.65	
	B	Gully	C	100		PVC		0.63	
	C								
	D								
	E								
	F								
OUTGOING PIPES	X	MH16	C	100		VC		0.81	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks:



Job Number: 16/328

Survey By: NA

Grid Ref:

Node Number: Valve Chamber

Cover Level:

Location: Highgate School, Dyne House, London

Year Laid: Z

Status: PR

Function:

Node Type: MH

Survey Date: 17/02/17

Manufacturer:

Grating:

COVER

Shape: R

Hinged:

Lockable:

Duty: M

Size:660x500

Toxic atmos:

SHAFT

Side Entry:

Regulating Courses:

Depth: 150

Size:620x460

Vermin:

CHAMBER

Soffit Type:S

No. of Step Irons: 4

No. of Ladders:

No. of Landings:

Size:2200x920

Const'n Code:CO

Depth of Flow:

Depth of Silt:

H of S:

	Pipe	U/S D/S node Reference	Shape	Pipe Size	Backdrop Diameter	Pipe Material	Lining Material	Depth from Cover (M)	Invert Level (M)
INCOMING PIPES	A								
	B								
	C								
	D								
	E								
	F								
OUTGOING PIPES	X	MH07	C	100		CI		2.90	
	Y								

CONDITION INFORMATION Enter Y if attention required. Use Remarks to clarify

Cover	Irons/Ladders	Shaft	Chamber	Benching	Other
-------	---------------	-------	---------	----------	-------

Remarks: X pipe only visible. Overall depth is 3.50m.



Photo 1, Location of MH01



Photo 2, View down MH01



Photo 3, Location of MH03



Photo 4, View down MH03



Photo 5, Location of MH04



Photo 6, View down MH04



Photo 7, Location of MH05



Photo 8, View down MH05



Photo 9, Location of MH06



Photo 10, View down MH06



Photo 11, View down MH07



Photo 12, Location of MH08



Photo 13, View down MH08



Photo 14, Location of MH10



Photo 15, View down MH10

