


GEOSHIELD Verification Report

VERIFICATION ITEM TWO



Above photo) all welded lap joints were verified using a pick and probe method.

Above shows the verification being carried out and the red arrows show the welded

lap joints. Passed and verified.

GEOSHIELD Verification Report

ADDITIONAL PHOTOGRAPHS



Roller used during install



Pudlo liquid membrane



Leister used during install



Reinforced corner detail