

GEOSHIELD Verification Report

VERIFICATION ITEM ONE



3. Photo evidence. Double sided tape visible. Pick and probe to ensure all the way around pile head and good consistent seal achieved.



GEOSHIELD Verification Report



VERIFICATION ITEM TWO

LOCATION/GRID LINE: Block D1 - Core - Middle and Upper

NOTES: All works visually inspected and only one area of damage

detected. Corner damaged during install of rebar. This was patch repaired and sealed

during inspection. Passed and verified.



1. Corner of Pudlo GP Ultra+ damaged

2. Patch repaired during inspection

GEOSHIELD Verification Report

VERIFICATION ITEM TWO



3. Patch repair made during inspection.

Excellent standard of installation and patch repair.

Passed and verified.