




Condition Survey Photos



Condition Survey Schedules



280 UPSTAIRS

Condition Survey Photos




Condition Survey Schedules



CRACK /
LOAD
PARTY?



Condition Survey Photos



Condition Survey Schedules



WHOLE
CORNER
PROTRUDING





BLOCK
FALLING
OUT



Condition Survey Photos



Condition Survey Schedules



Condition Survey Schedules



Condition Survey Photos



kink
in
window



CRACKING
FROM
OLD
BRACKET
PLATING


Condition Survey Schedules






Condition Survey Schedules




CORRODED
REINFORCE



FRONT
OUT.



LOW-LEVEL
CRACKING





CUT OUT
PARAPET
- SLIP -

CRACK

ROCK
BAR?

Condition Survey Photos



DR. DOOR
PANELED



12-15 mm




DISLOBBED

Condition Survey Schedules



CRACK



CRACK



CR.



DISLODGED

- PROXY WALL
PIERCEMENT CRACK / PHASE




DISLODGED



Condition Survey Photos





DISLODGED
- OVER HEATED CURE




WASHING
OUT

POX REPAIR

Condition Survey Schedules





Condition Survey Photos



MOSS ON
CILL
- COARDED
PLANT



Condition Survey Schedules



Condition Survey Photos

- TOWER ROOF.
- TOWER - FIBREGLASS ROOF
 - KICKING TO CONCRETE
- SILICONE @ JOINTS



Condition Survey Schedules



AE SIDE LIGHT

PATCH
REPAIR.




PK'S



CRACK
9
FROM
GILL
FLOOR
2

Condition Survey Photos




Condition Survey Schedules



Condition Survey Photos



✓ PREPARED
PROFILE
- MIX TO MATCH
ORIGINAL - WHITE CEMENT
- SILVER SAND } MIX
IN
GREY?
- TEST:



Roger Mears Architects LLP

Union Chapel
Compton Avenue
London N1 2XD
Tel: 020 7359 8222

www.rmears.co.uk

Company Number: OC366956
Registered Address: 1 Vincent Square, SW1P 2PN

R O G E R M E A R S A R C H I T E C T S

Haringey
LONDON