

Condition 5

Cleaning trials

Existing louvred timber turret



5.1
South-east elevation
Timber mostly in sound condition, small
localised repairs marked
Paint removal commenced, to be repaired and
redecorated in line with method statements



5.2
North-east elevation



5.3
South-west elevation



5.4
North-west elevation