



Internal damp and leaks to the external wall and ceiling



Structural cracks of more than 1cm width to side extension that have been taped over



External cracks to render walls



Uneven internal floors of 50 - 75mm differential across rooms



Evidence of structural subsidence, above right corner of patio door which is 70mm lower



Poor condition of timber windows including rot



Poor condition of the existing roof