

4

Existing Building

4.4

Key Internal Spaces - Council Chamber

Council Chamber

Features

- Fanned Ceiling
- Timber panelling
- Public Gallery
- Glazing

Materiality

- Fanned Ceiling
- Timber panelling with brass inlays
- Public Gallery
- Glazing

Pre-Enabling Works Condition

- Asbestos ceiling
- Timber panelling with brass inlays - brass tarnished
- Non-Original carpet
- Vertical Blinds
- Original brass clock removed

Post-Enabling Works Condition

- Asbestos ceiling removed
- Carpet Removed & Blinds Removed (Curtain track retained)



Top
Historical Images

Middle
Pre-Enabling Works

Bottom
Post-Enabling Works