


PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-01
HEIGHT	2.566
WIDTH	0.593 by 5



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	5	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	15
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	5	5				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-02
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-03
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-04
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-05
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-06
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-07
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-08
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-09
HEIGHT	1.645
WIDTH	0.608 by 4



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	4	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM		PANES	8
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	4	4				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-10
HEIGHT	1.645
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM		PANES	12
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-11
HEIGHT	1.645
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM		PANES	12
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-12
HEIGHT	1.645
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM		PANES	12
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-13
HEIGHT	1.645
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM		PANES	12
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES	GWP to left panes				

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						

KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised
One panel not visible

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------


ELEVATION	WEST
FLOOR	3RD FLOOR
WIN NO	W3-14
HEIGHT	2.540
WIDTH	2.900



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR	1	
DOUBLE DOOR		



GLAZING		FILM		PANES	5
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER	1	1				
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE	1	1				

KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------


ELEVATION	WEST
FLOOR	3RD FLOOR
WIN NO	W3-15
HEIGHT	2.540
WIDTH	2.900



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		



GLAZING		FILM		PANES	5
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER	2	2				
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-16
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM		PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-17
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM		PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	3RD FLOOR
WIN NO	W3-18
HEIGHT	2.566
WIDTH	0.593 by 6



MATERIAL	
ALUMINIUM	
STEEL	☒
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT	6	
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM		PANES	18
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒		
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	6	6				
DOOR FURNITURE						

KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
Divided by concrete mullions
Galvanised

PHOTOGRAPHIC RECORD			
ELEVATION	1		