

HARINGEY CIVIC CENTRE



WINDOW CONDITION SURVEY

Appendix



fig 1 Bedding compound in poor condition



fig 2 Bedding compound in poor condition



fig 3 Failure at mullion and transom junction



fig 4 Evidence of water penetration



fig 5 Separating at transom glazing bar



fig 6 Separating at transom glazing bar



fig 7 Separating at transom glazing bar



fig 8 Separating at transom glazing bar



fig 9 Separating at transom glazing bar



fig 10 Splitting of corner post mullion



fig 11 Distortion of frame



fig 12 Evidence of water penetration



fig 13 Daylight seen through mullion



fig 14 Condition of internal surface finishes and pitting



fig 15 General condition of internal surfaces



fig 16 Poor condition of external surfaces



fig 17 Failure of previous spray application externally



fig 18 Generally poor condition of external surfaces



fig 19 Example of opening mechanism



fig 20 Example of extending hinge mechanism

CONTACT DETAILS

The company head office address is Sutcliffe House, 77 Milton Road, Croydon, CR0 2BJ

Telephone : 020 8665 5335

Email : info@asws.co.uk

In addition, please feel free to browse our website at your convenience; www.asws.co.uk

