


PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-01
HEIGHT	2.970
WIDTH	2.750



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	5
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-02
HEIGHT	2.900
WIDTH	3.525



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-03
HEIGHT	2.900
WIDTH	3.525



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-04
HEIGHT	2.900
WIDTH	3.525



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-05
HEIGHT	2.900
WIDTH	3.525



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS		POOR ACCESS	☒
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating
Steel plate panels at bottom badly corroded

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-06
HEIGHT	2.980
WIDTH	1.564



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS		POOR ACCESS	☒
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	3
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	DG-07 External
HEIGHT	2.900
WIDTH	7.225



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS		POOR ACCESS	☒
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR	3	

GLAZING		FILM	☒	PANES	13
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE	3	3				




KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating
Doors in poor condition, closer and plates corroded

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-08
HEIGHT	2.970
WIDTH	2.750



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	5
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating
Bottom panels blanked off

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-09
HEIGHT	2.070
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE	2	2				
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-10
HEIGHT	2.070
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER	1	1				
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						
PEG STAY						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-11
HEIGHT	2.070
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE	2	2				
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						
PEG STAY						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-12
HEIGHT	2.070
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE	2	2				
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						




KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-13
HEIGHT	2.070
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS		POOR ACCESS	
NO ACCESS	☒	SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE	2	2				
VENT LOCK						
FOLDING OPENER	1	1				
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-14
HEIGHT	2.070
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	3	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		2				
HANDLE	2	2				
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-15
HEIGHT	2.070
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE	2	2				
VENT LOCK						
FOLDING OPENER	1	1				
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						

KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-16
HEIGHT	2.070
WIDTH	3.524



KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating
Separted by partition

PHOTOGRAPHIC RECORD			
ELEVATION	1		

MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	


OPENING VENTS		FIXED
TOP HUNG	3	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE	2	2				
VENT LOCK						
FOLDING OPENER	2	2				
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	EAST
FLOOR	GROUND FLOOR
WIN NO	WG-17
HEIGHT	2.070
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	6
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE	2	2				
VENT LOCK						
FOLDING OPENER	1	1				
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	NORTH
FLOOR	GROUND FLOOR
WIN NO	WG-18
HEIGHT	
WIDTH	



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR	1	

GLAZING		FILM	☒	PANES	7
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE	1	1				


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-19
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	9
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	4	4				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
New replacement window

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-20
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	☒
POOR	

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	10
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		2				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	2	2				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
New replacement window

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-21
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	4	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	10
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER	2	2				
SPRING CATCH	2	2				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-22
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	4	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	10
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER	2	2				
SPRING CATCH	2	2				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-23
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	4	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	10
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		3				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	2	2				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-24
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	4	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	10
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER	2	2				
SPRING CATCH	2	2				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-25
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	4	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	10
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		2				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	2	2				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-26
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	4	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	10
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒	☒	☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		2				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	2	2				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-27
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	4	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	10
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCUR	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒		☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH	2	2				
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-28
HEIGHT	
WIDTH	



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR	1	

GLAZING		FILM	☒	PANES	9
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒		☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE	1	1				


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-29
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	8
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒		☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating
Vent axia top pane

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-30
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	8
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒		☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	WEST
FLOOR	GROUND FLOOR
WIN NO	WG-31
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	1	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	8
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒		☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR		1				
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	SOUTH
FLOOR	GROUND FLOOR
WIN NO	WG-32
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	5
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒		☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER	2	2				
SPRING CATCH						
DOOR FURNITURE						


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	SOUTH
FLOOR	GROUND FLOOR
WIN NO	WG-33
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG		
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR	1	

GLAZING		FILM	☒	PANES	7
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒		☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER						
SPRING CATCH						
DOOR FURNITURE	1	1				


KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating
Doors in poor condition

PHOTOGRAPHIC RECORD			
ELEVATION	1		

PROJECT	S-2310	HARINGEY CIVIC CENTRE
---------	--------	-----------------------

ELEVATION	SOUTH
FLOOR	GROUND FLOOR
WIN NO	WG-34
HEIGHT	2.970
WIDTH	3.524



MATERIAL	
ALUMINIUM	☒
STEEL	
CONDITION	
GOOD	
FAIR	
POOR	☒

ACCESS			
GOOD ACCESS	☒	POOR ACCESS	
NO ACCESS		SECONDARY	

OPENING VENTS		FIXED
TOP HUNG	2	
HORIZONTAL PIVOT		
SINGLE DOOR		
DOUBLE DOOR		

GLAZING		FILM	☒	PANES	5
SINGLE	☒	DOUBLE		UNGLAZED	
	CLEAR	OBSCURE	WIRED	SAFETY	MIXED
TYPE	☒				
	PUTTY	BEAD	INTERNAL	EXTERNAL	MIXED
GLAZING		☒		☒	
NOTES					

IRONMONGERY						
	ORIGINAL REQUIREMENT	NOW PRESENT	MISSING OR BROKEN	ODD		TYPE
TELEFLEX GEAR						
HANDLE						
VENT LOCK						
FOLDING OPENER						
CAM FOLLOWER	2	2				
SPRING CATCH						
DOOR FURNITURE						

KEY	
	BROKEN PANE
	FILMED
	CORROSION
	AREA OF CONCERN (SEE NOTES)

NOTES
All surfaces showing signs of deterioration
Sections separating

PHOTOGRAPHIC RECORD			
ELEVATION	1		