


Proposals to be read with reference to
The following documents and drawings:

- Dry Rot and Timber Investigation and Methodology Statement [Hunter & Rostron - H&R] 18/11/24
- Level 2 Historic Building Record [H&R] 19/12/24
- Heritage Statement for Remediation of decayed and Dry Rot infested Timbers and repairs to Exterior [H&R] 09/01/25
- Structural Survey Report [Bailiss & Co] 25/08/24
- Initial Condition Survey [H&R] 18/12/24

Drawings based on
Hutton & Rostron
Facade Masonry Report




37 North Road, N6 - Front (east) elevation
Façade masonry condition investigation
28 November 2024

Drawings as Existing

Proposals to be read with reference to
The following documents and drawings:

- Dry Rot and Timber Investigation and Methodology Statement [Hunter & Rostrun - H&R] 18/11/24
- Level 2 Historic Building Record [H&R] 19/12/24
- Heritage Statement for Remediation of decayed and Dry Rot infested Timbers and repairs to Exterior [H&R] 09/01/25
- Structural Survey Report [Bailiss & Co] 25/08/24
- Initial Condition Survey [H&R] 18/12/24

Drawings based on
Hutton & Rostron
Facade Masonry Report




37 North Road, N6 - Front (east) elevation
Façade masonry condition investigation
28 November 2024

Drawings as Existing

Proposals to be read with reference to
The following documents and drawings:

- | | |
|---|----------|
| • Dry Rot and Timber Investigation and Methodology Statement
[Hunter & Rostrun - H&R] | 18/11/24 |
| • Level 2 Historic Building Record
[H&R] | 19/12/24 |
| • Heritage Statement for Remediation of decayed and Dry Rot infested Timbers and repairs to Exterior
[H&R] | 09/01/25 |
| • Structural Survey Report
[Bailiss & Co] | 25/08/24 |
| • Initial Condition Survey
[H&R] | 18/12/24 |

Drawings based on
Hutton & Rostron
Facade Masonry Report



37 North Road, N6 - Front (east) elevation

Façade masonry condition investigation
28 November 2024

Drawings as Existing

