

9 Muswell Hill

Conditions discharge site investigations

Contents

1.0	First floor fireplaces
2.0	Ground floor WC walls

Site investigations

First Floor Fireplaces



Front bedroom fireplace

- Brick visible behind modern concrete and tile surround.
- Remains of clay fire back when fireplace was in use inset into brickwork.



Rear bedroom fireplace

- Timber frame visible within opening to hold timber board in front.
- Remains of clay fire back when fireplace was in use inset into brickwork.



Rear bedroom fireplace

- Tile removed to side of fireplace showing brick behind



Rear bedroom fireplace

- Tile removed to inner side of fireplace showing brick behind.
- Modern concrete backing to tiles.


Site investigations

Ground floor WC walls



WC walls

- Modern concrete blockwork construction of WC walls with gypsum plaster finish visible from opening up works.



WC plan

- Location of opening up works in modern wall shown with red arrow.