



A photograph showing significant structural damage and decay in an interior space. The upper portion of the image captures a ceiling in disrepair, with dark, weathered wooden planks and exposed joists. Several white pipes run across the ceiling, and a white electrical conduit is visible. The lower portion shows a wall with peeling blue and white paint, revealing the underlying masonry or plaster. A white, ribbed object, possibly a pipe or vent, is visible in the bottom right corner. The overall scene suggests a neglected or abandoned building.

CALCULATED BY T. J. W. ABOVE BATHROOM.



OTHER THIS MASONRY STRUCTURE IS EXISTING.
EXISTING.






LOCATION FOR ANDY VENT



DOCTWORK & BULKHEAD BETWEEN DINING ROOM & KITCHEN
EXTEND WALL





DUCTWORK TO REPAIR WALL & LICK REMOVAL

