St William
Designed for life

MEMORANDUM
Via Email

To Matthew Pannett **Date** 02/11/2023 - **Rev C**

From Chris Davis

Subject: Clarendon Road Phase 3 – Block D1 & D2 Soil Verification

Dear Matthew,

This memo has been produced by St William to accompany the submission of the soil verification report titled *5196431_Block D1 & D2 Verification Report,* which has been issued to LB Haringey in support of the partial discharge of Condition 31: Land Contamination attached to planning permission HGY/2017/3117. This memo supersedes the initial Installed Soils Memo Rev A issued on the 16th of August 2023.

The Atkins report identifies five testing zones where installation of the HHSL is required and to be photo evidenced in accordance with the build-up noted in the Atkins remediation strategy. For zones 1, 2 and 3 this record is present within the Atkins report pages 41 to 48. At the time of witnessing for these areas zones 4 & 5 were not ready and so were subsequently completed by the landscaping contractor.

Overleaf is a key plan overleaf identifying the zones testing/HHSL zones and another identifying positions from where images have been taken. LB Haringey have requested that this updated memo Rev B be provided to yourselves and for your report to be updated to confirm that you have seen evidence of the HHSL installation for all areas.

Regards,

[redacted]

Chris Davis
Senior Technical Manager

Testing Key Plan



Image Key Plans – Zones 4 & 5





Image Key Plans – Zones 1 & 3





View 1 – CBL & Geotextile Marker Layer

View 2 – Geotextile Marker Layer

View 3 – Topsoil Depth

View 4 – Geotextile Marker Layer

View 5 – Topsoil Depth

View 6 – Subsoil Depth

<u>View 7 (Zone 1) – Response to Edward Ritchie's email 12/09/2023</u> - requesting photographic evidence that the additional topsoil requirement identified in Atkins report ***5196431 Block D1 D2 Verification Report*** Photo #9 page 46 is provided.

<u>View 8 (Zone 3) – Response to Edward Ritchie's email 12/09/2023</u> - requesting photographic evidence that the complete topsoil requirement is installed as identified in Atkins report ***5196431 Block D1 D2 Verification Report*** Photo #10 page 47.