





KEY PLAN



01 South Elevation B3
1:100@A3; 1:50@A1



02 South Elevation B4
1:100@A3; 1:50@A1

0 5 10 M

Notes

Facade to be repaired using replacement concrete blocks to match existing.
See condition survey for extent of works.

Revisions

A	18/01/2023	Shop signs updated
B	16/02/2023	Notes revised
C	23/02/2023	Signboards revised

St. Mark's Methodist Church
High Rd, London N17 6QB

Proposed South Side Elevations

ROGER MEARS ARCHITECTS LLP
Union Chapel, Compton Avenue London N1 2XD

rma@rmears.co.uk tel 020 7359 8222
www.rmears.co.uk

© Roger Mears Architects LLP 2022

Date	Scale	Job No.	Dwg No.	Rev.
July 2022	1:100@A3 1:50@A1	2146	L(00)212 C	