


KEY:

Refer to Outline Interior Finishes / Features Condition and Scope of Works HCC-HBA-CC-XX-SH-A-400001

- Repair of existing in-situ staircase and bridge structure and fascias clad in stone
- Repair of existing staircores in terrazzo
- Existing external to be made good, cleaned and repainted.
- Repair of existing Roof access ladder

Copyright Hawkins\Brown Architects  
No implied licence exists. This drawing should not be used to calculate areas for the purposes of valuation. Do not scale this drawing. All dimensions to be checked on the site by the contractor and such dimensions to be their responsibility. All work must comply with relevant British Standards and Building Regulations requirements. Drawing errors and omissions to be reported to the architect. To be read in conjunction with Architect's specification and other consultant information.

| Rev | Description    | Date     |
|-----|----------------|----------|
| P1  | Planning Issue | 05.04.23 |



159 St John Street  
London EC1V 4QJ

mail@hawkinsbrown.com  
hawkinsbrown.com

Hawkins\Brown

Project  
Haringey Civic Centre  
High Rd,  
Wood Green,  
N22 8LE

Drawing  
Level 02 - Stairs & Ramps Civic  
Centre repair plan

Scale @ A1  
1 : 200

Date  
15.03.23

Drawn By  
EV

Checked By  
JM

Job Number  
190149

Status  
S2

Purpose of Issue  
Issued for  
Information

Drawing No.  
HCC-HBA-CC-02-DR-A-248102

Rev  
P1

