



WHITECODE
CONSULTING

Tayna Farrell
Ardmore Group
6 Wharf Studios
28 Wharf Road
London
N1 7GR

24 July 2023

Dear Tayna,

RE: Hornsey Town Hall, Town Hall Square External Lighting

I am writing in response to queries relating to the external lighting design and installation within the above areas on the aforementioned site.

We have recently received the below document produced by LPA lighting and Energy Solutions:

HTH_Exterior_Lux Report_REV1D_24.07.23

From reviewing this document, it has demonstrated the lighting is inadequate for the main pathways into the site from The Broadway where CCTV coverage is required. A minimum of 5 lux is required here with good uniformity values to ensure Secured By Design principles are adhered to. It appears some of the ancillary pathways in close proximity to the Town Hall could achieve adequate lighting if the flux levels are increased within the calculations.

We previously undertook lighting calculations for these areas with a more appropriate column luminaire by Selux which achieved adequate lighting performance in these areas.

Should you have any queries, please do not hesitate to contact the undersigned.

Yours sincerely

**For and on behalf of
Whitecode Consulting Ltd**

Jamie Mitchell
Associate



**BUILDING SERVICES
DESIGN CONSULTANTS**