


4

Existing Building


4.3

Areas of Historical Significance

Historic Floor Plans
The Architect & Surveyor - 1958




Areas of Historical Significance Plans
Montagu Evans






KEY	
High	Medium
Low	Neutral
Detracting	

Historical Alterations Plans
Montagu Evans



KEY	
Post 1958 Alterations	Infill and Alterations to corridor partitions
1989 (HGY/1989/1036)	1986 (HGY/39236)
1990 (HGY/49088)	2001 (64299)

Second Floor



Third Floor (Attic)

4

Existing Building

4.4

Key Internal Spaces - Lobby


Entrance Lobby

- Features**
- Triple height atrium
 - Self-supporting, Spiral staircase with link bridge to Council Chamber
 - Glazed to promote transparency
 - Memorial Plaque
 - Garden adjacent to entrance

- Materiality**
- Travertine stone cladding
 - Timber wall panelling with brass inlays
 - Stone tiled flooring

- Pre-Enabling Works Condition**
- Extensive cracking/chipping in stone tiled flooring
 - Brass inlays tarnished
 - Spotlights and recessed strip-lights in bridge require upgrading

- Post-Enabling Works Condition**
- Ceiling below bridge removed
 - Carpet Removed & Blinds Removed



Top

Historical Images

Middle

Pre-Enabling Works

Bottom

Post-Enabling Works