

4

Existing Building

4.4

Key Internal Spaces - Committee Rooms and Mayors Office

Committee Rooms & Mayors Parlour

- Features
- Fanned Ceiling

Timber panelling

Public Gallery

Glazing
- Materiality
- Fanned Ceiling

Timber panelling with brass inlays

Public Gallery

Glazing
- Pre-Enabling Works Condition
- Asbestos ceiling

Timber panelling with brass inlays - brass tarnished

Non-Original carpet

Vertical Blinds

Original brass clock removed
- Post-Enabling Works Condition
- Asbestos ceiling removed

Carpet Removed & Blinds Removed (Curtain track retained)

Large Committee Room



Top
Historical Images

Middle
Pre-Enabling Works

Bottom
Post-Enabling Works

Committee Room Corridor



Mayor's Parlour



Robing Room

