

- ## CONSTRUCTION



- All external glazing to be double glazed sealed units

- Background ventilation to be in accordance with trickle vent sizes specified on schedule plan.

RISK SCHEDULE	
ITEM	DESCRIPTION OF RISK & ACTION
	Activity: Ceiling Mounted Cooker Hood Installation Boiler and Kitchen Appliance Installation Lintel Installation Risk: Injury due to fall from height, incorrect handling, falling objects Activity: Canopy/Porch/ Window Roof Installation Stairs Installation Large Glazing Installation Risk: Injury due to fall from height, incorrect handling, falling objects, crushing

Key Plan

powarchitects

15 Bluelion Place, London, SE1 4PU
enquiries@pow-architects.com
020 3176 6620

Project: Townsend Yard

Title: Elevation-Front-West

Job No 1240	Drawn by FB	Scale As	Number 1006	Revised C
Date MARCH 1920	Checked by MO	indicated@A1		