

Fountain Bowl

As the full method statement ALT-730 denotes, the main bowl of the fountain it to be refurbished in-situ, a brief overview of the work is denoted as a positive addition to the method statement but is not to be read as the full scope of works for the restoration



Generally border is in good condition with one bay showing a large section of stone damage which is to be replaced with matching stone. The remainder is to be light repairs and cleaning only.



Existing paint shown to be cracking and peeling. To be cleared and removed back to stone for new paint.



Tiles shown in general good condition. Any loose or unbedded tiles to be reset, any missing tiles to be replaced with replica matching tile.



Stone border in general good condition with some detailing missing to be reinstated and cracks infilled. Majority of stone requires cleaning only.

Typical condition of stone fins - shape still distinguishable with some signs of age - no works.

Some fins show missing sections of larger cracks while still distinguishable, cracks are to be filled and fins repaired