

^ Subgrades of CBR less than 5% are often too fine to permit sufficient infiltration.

Revision