



Church Works

- 1. Repairs to the existing roof where required including leak repairs and replacing missing terracota crestings
- 2. Cleaning of external elevations
- 3. Hard and soft landscaping
- 4. Stone/ Brickwork restoration where required. Like for like brickwork would be laid to match the surrounding bond, using mortar with flush joints



NOTE
This drawing is copyright. Do not scale off dimensions. All dimensions are to be checked on site by contractor. Contractor to report any dimensional discrepancies, errors or omissions prior to commencing on site.



suggested new tree to be provided via S106

I			
H			
G			
F			
E			
D			
C			
B			
A	21.10.23	Top floor door to amenity omitted	NA
REV	DATE	DETAILS	BY

CLIENT SIGNATURE
CLIENT
-

PROJECT
Braemar Avenue, Wood Green

DRAWING TITLE
Proposed Elevation C

STATUS
Planning Application

DATE	SCALE
May 2022	1:200@A1;1:400@A3

JOB NO.	TYPE	DRAWING NO.	REVISION
1802	GA	042	A

spacelab

18 Wenlock Road London N1 7TA
+44 (0)20 7033 3450 www.spacelab.co.uk