


- NOTE
1. This drawing is copyright.
 2. All dimensions must be checked on site before proceeding.
 3. Dimensions of new work are to be adjusted to suit the existing building where necessary. Do not assume that the existing structure or details are plumb, square or level.
 4. The contractor must report any discrepancies to the architect before proceeding.
 5. All products are to be used strictly in accordance with the manufacturer's instructions.



KEY

- Potential compartment line using existing wall position - 60 mins (suitability to be investigated on site)
- Desirable compartment line - 60 mins (options to be investigated on site)
- Upgrade existing door leaf to achieve FD30S (Aspirational)
- Install new FD60S door leaf into existing opening (Aspirational)
- Replace existing door with new door to achieve FD60S (Aspirational)
- Replace existing door with new door to achieve FD30S
- Fire escape route
- High risk activity/space in relation to fire protection, integrity, and escape.
- MEND Funded Works
- Upgrade existing door leaf to achieve FD60S (Aspirational)

B 11/23 Key Updated
A 10/23 Notes amended to co-ordinate with door schedule
REVISIONS

Rodney Melville + Partners
CHARTERED ARCHITECTS
HISTORIC BUILDING CONSULTANTS

10 EUSTON PLACE
LEAMINGTON SPA
WARWICKSHIRE
CV32 4LJ
T 01926 881311
F 01926 451766

E architects@rmpuk.com
www.rmpuk.com

Rodney Melville and Partners Limited

Client
London Borough of Haringey Council

Project
Bruce Castle

Title
Second Floor Plan
Outline Door Upgrade Proposals

Scale 1:100 @ A1	Job No 7440
Date April 2023	Draw No 307
Drawn HB/RG	Rev B

S19.D02: Existing modern door leaf is to be replaced with new FD60s leaf. Refer to Second floor door schedule for information.

S18.D01: Works are required to upgrade triangular fanlight above this door. Refer to Second floor door schedule for information.

S1.D01: Works are required to upgrade fanlight above this door. Refer to Second floor door schedule for information.

S19.D01 : Fire door retainer to be fitted to base of this leaf which will release upon sounding of the Fire alarm. Refer to Second floor door schedule for information.

S6.D07: New FD30s door to be inserted into existing opening. Refer to Second floor door schedule for information.

SECOND FLOOR PLAN - OUTLINE DOOR UPGRADE PROPOSALS

0 1 2 3 4 5m