

FIRST FLOOR PLAN - OUTLINE DOOR UPGRADING PROPOSALS



F20.D02 : Replace existing modern door leaf with new FD60s. Refer to First floor door schedule for information.

F17.D02 + F20.D01 : Replace existing modern door leafs with new FD60s leafs. Fire door retainers to be fitted to base of these doors which will release upon sounding of the Fire alarm. Upgrade works required to fanlight over F20.D01. Refer to First floor door schedule for information.

F18.D01 : New FD60s fitted into existing opening. Upgrade works required to fanlight. Refer to First floor door schedule for information.

F17.D01 : Fire door retainer to be fitted to base of this leaf which will release upon sounding of the Fire alarm. Fanlight above this opening is to be upgraded. Refer to First floor door schedule for information.

F1.D01 : This door to be fitted with new combined overhead closer and hold open device linked to fire alarm. Refer to First floor door schedule for information.

F16.D01 : Fire door retainer to be fitted to base of this leaf which will release upon sounding of the Fire alarm. Refer to First floor door schedule for information.

F15.D01 : Existing door leaf to be replaced with new FD30s leaf. This door to be fitted with combined overhead closer and hold open device linked to fire alarm. Refer to First floor door schedule for information.

F15.D03 : This door to be fitted with new combined overhead closer and hold open device linked to fire alarm. Refer to First floor door schedule for information.

F15.D02 : New 60min infill to be provided behind existing door leaf on F14 side of this opening. Refer to First floor door schedule for details

F13.D02 : New purpose made FD60s door to be installed within existing opening. Fire door retainer to be fitted to base of door which will release upon sounding of the Fire alarm. Refer to First floor door schedule and drawing no: 7440-313.

F4.D03 : This door to be fitted with new combined overhead closer and hold open device linked to fire alarm. Refer to First floor door schedule for information.

F5.D01 : Existing door leaf to be replaced with new FD30s leaf. Refer to First floor door schedule for works required to this door and opening.


F11.D01 : This door to be fitted with new combined overhead closer and hold open device linked to fire alarm. Refer to First floor door schedule for information.

F10.D01 : This door to be fitted with new combined overhead closer and hold open device linked to fire alarm. Refer to First floor door schedule for information.

F13.D01 : New purpose made FD60s door to be installed within existing opening. This door to be fitted with combined overhead closer and hold open device linked to fire alarm. Refer to First floor door schedule and drawing no: 7440-312.

F9.D01 : Existing door leaf to be re-hung to open into room F6/7/8. Door to be fitted with new combined overhead closer and hold open device linked to fire alarm. Refer to First floor door schedule for information.

- NOTE
1. This drawing is copyright.
 2. All dimensions must be checked on site before proceeding.
 3. Dimensions of new work are to be adjusted to suit the existing building where necessary. Do not assume that the existing structure or details are plumb, square or level.
 4. The contractor must report any discrepancies to the architect before proceeding.
 5. All products are to be used strictly in accordance with the manufacturer's instructions.



KEY

- Potential compartment line using existing wall position - 60 mins (suitability to be investigated on site)
- - - Desirable compartment line - 60 mins (options to be investigated on site)
- Upgrade existing door leaf to achieve FD30S (Aspirational)
- Install new FD60S door leaf into existing opening (Aspirational)
- Replace existing door with new door to achieve FD60S (Aspirational)
- Replace existing door with new door to achieve FD30S
- Fire escape route
- High risk activity/space in relation to fire protection, integrity, and escape.
- MEND Funded Works
- Upgrade existing door leaf to achieve FD60S (Aspirational)

B 11/23 Key Updated
A 10/23 Notes updated in line with door schedule
REVISIONS

Rodney Melville + Partners
CHARTERED ARCHITECTS
HISTORIC BUILDING CONSULTANTS

10 EUSTON PLACE
LEAMINGTON SPA
WARWICKSHIRE
CV32 4LJ
T 01926 881311
F 01926 451766

E architects@rmpuk.com
www.rmpuk.com

Rodney Melville and Partners Limited

Client
London Borough of Haringey Council

Project
Bruce Castle

Title
First Floor Plan
Outline Door Upgrading Proposals

Scale	1:100 @ A1	Job No	7440
Date	June 2023	Dwg No	306
Drawn	HB/RG	Rev	B