



30 January 2024

Samuel Elliott
Heritage Potential

Job Code: 001550 Bruce Grove youth Space

Dear Sam,

Planning Consultation - LB Haringey - HGY/2023/0912, 10 Bruce Grove, Tottenham, London, N17 6RA

Ref:

3F Method statement and specification of repairs and replacement to front door's fan lights and sidelight frames.

Action:

Refer to drawing A-1220.

R1 - Window frames in generally poor condition - Prepare and repaint windows (a lime based breathable paint) generally colour to match existing

R2 - Rotten areas of window frame -Cut out rotten timber to bottom rail of sash and scarf in new hardwood timber piece and repaint (a lime based breathable paint) to match existing

R3 - Door in poor condition - Prepare and redecorate front door. Colour TBC

R4 - Front door fan lights and sidelight frames in poor condition - Prepare and repaint (a lime based breathable paint) side lights and fanlight to front door

R5 - Poor quality glazing to door side lights and fan lights - Replace Georgian wired glass to side lights and fanlight with clear toughened glass

Contractor to review on site & prepare method statement.

Timing:

Prior to commencement of relevant part of the development

Yours Sincerely
Louis Stocks
ADP