

Alexandra Palace - Existing Conditions



Like-for-like repair/replacement of stone steps.



Existing undercroft needs to be secured. Stairs need repairing.



Like-for-like repairs/replacement to vaulted arch brickwork



New like-for-like riser stone step to achieve new drainage falls



Like-for-like repairs to Southern brick wall adjacent to the 'CUFOS' building



Like-for-like repairs/replacements to brick walls either side of stairs




Like-for-like replacement to lights




Alexandra Palace - Proposed Look & Feel



HiSec SR2 (B3) Rated Fencing



Infill panel detail - panel could be timber/metal/other material



'Jontun' Aluminium Grey paint to match other external metalwork




Linear slot drains



Alternative metal infill panel and top rail design aesthetic



Corduroy strips - Multitread Tactile Indicators



Mastic Asphalt Flooring



Blister surface studs - alternative to corduroy strips



Dales sigma aluminium fascia and concealed gutter - reflects steel profile