
COMPUTER AIDED DRAWING - AVOID MANUAL MODIFICATION

THIS DRAWING MUST NOT BE SCALED,
ALL DIMENSIONS TO BE CHECKED ON SITE.

DISCLAIMER
The information shown within is given without obligation, or warranty, the accuracy thereof cannot be guaranteed. No liability of any kind whatsoever is accepted by Cable Tracing Services Limited its operatives for any error or omission.
Safe digging practices, in accordance with HS(G)47 must be used to verifiy and establish the actual position of the statuary undertaker's apparatus on site before any mechanical plant is used. It is your responsibility to ensure that this information is provided to all persons either direct labour or contractors. Any error found should be reported immediately to the management before any works are to be carried out.

Notes

This 3D Model has been drawn from point cloud data taken from the inside surfaces of the sewer structures.



ALL MEASUREMENTS ARE APPROXIMATE AND SHOULD BE VERIFIED ON SITE BY FOLLOWING THE SAFE DIGGING PRACTICES SET OUT IN THE HSG47 GUIDE.
COORDINATE SYSTEM SETTINGS:
SYSTEM - UNITED KINGDOM ZONE - OS NATIONALGRID(OSTN02)
DATUM - ORDNANCE SURVEY GEOID MODEL - (OSGM02)
COORDINATE ORDER - EAST FIRST - NORTH LAST

REFERENCE DRAWINGS.

DRAWING No	TITLE

Project Title: Cranwood House

Client: McAllister Group

Discipline:		Scale:	Project Phase:
Topographical Survey & Laser Scanning		1:200@ A1	Survey Information
Drawing Originator:		Drawn By:	Approval By:
Cable Tracing Services Limted		DMB	JMB
Drawing No:	Revision:	Drawn Date:	Check Date:
CTS-MC 0129 20-21(1)	B	15-12-20	17-06-21

1m 0 10m 20m
SCALE - 1:200


COMPUTER AIDED DRAWING - AVOID MANUAL MODIFICATION

THIS DRAWING MUST NOT BE SCALED,
ALL DIMENSIONS TO BE CHECKED ON SITE.

DISCLAIMER
The information shown within is given without obligation, or warranty, the accuracy thereof cannot be guaranteed. No liability of any kind whatsoever is accepted by Cable Tracing Services Limited its operatives for any error or omission.
Safe digging practices, in accordance with HS(G)47 must be used to verifiy and establish the actual position of the statuary undertaker's apparatus on site before any mechanical plant is used. It is your responsibility to ensure that this information is provided to all persons either direct labour or contractors. Any error found should be reported immediately to the management before any works are to be carried out.

Notes

This 3D Model has been drawn from point cloud data taken from the inside surfaces of the sewer structures.



Taken From TW Drawing
MH - 3101F
CL - 90.47
IL - Not Supplied
DTI - Not Supplied

MH3101

PIPE 1 - 1243mm

1243mm

300mm

305mm

MH3103

PIPE 4 - 300mm

PIPE 3 - 305mm

PIPE 2 - 300mm

90.2m

300mm

Survey abandoned: survey abandoned due to crawler unable to get pass debris in pipe, pipe has been jetted multiple times.

Cra

300mm

CL-90.53
IL-87.48

CL-90.48
IL-87.48

300mm

Tk

St James's C of E Primary School

El

Sub Sta

02

1m 0 10m 20m

SCALE - 1:200

ALL MEASUREMENTS ARE APPROXIMATE AND SHOULD BE VERIFIED ON SITE BY FOLLOWING THE SAFE DIGGING PRACTICES SET OUT IN THE HSG47 GUIDE.
COORDINATE SYSTEM SETTINGS:
SYSTEM - UNITED KINGDOM ZONE - OS NATIONALGRID(OSTN02)
DATUM - ORDNANCE SURVEY GEOID MODEL - (OSGM02)
COORDINATE ORDER - EAST FIRST - NORTH LAST

N


REFERENCE DRAWINGS.

DRAWING No	TITLE

Project Title: Cranwood House

Client: McAllister Group

Discipline:		Scale:	Project Phase:
Topographical Survey & Laser Scanning		1:200@ A1	Survey Information
Drawing Originator:		Drawn By:	Approval By:
Cable Tracing Services Limted		DMB	JMB
Drawing No:	Revision:	Drawn Date:	Check Date:
CTS-MC 0129 20-21(2)	B	15-12-20	17-06-21





COMPUTER AIDED DRAWING - AVOID MANUAL MODIFICATION

THIS DRAWING MUST NOT BE SCALED,
ALL DIMENSIONS TO BE CHECKED ON SITE.

DISCLAIMER
The information shown within is given without obligation, or warranty, the accuracy thereof cannot be guaranteed. No liability of any kind whatsoever is accepted by Cable Tracing Services Limited its operatives for any error or omission.
Safe digging practices, in accordance with HS(G)47 must be used to verifiy and establish the actual position of the statuary undertaker's apparatus on site before any mechanical plant is used. It is your responsibility to ensure that this information is provided to all persons either direct labour or contractors. Any error found should be reported immediately to the management before any works are to be carried out.

Notes

This 3D Model has been drawn from point cloud data taken from the inside surfaces of the sewer structures.

ALL MEASUREMENTS ARE APPROXIMATE AND SHOULD BE VERIFIED ON SITE BY FOLLOWING THE SAFE DIGGING PRACTICES SET OUT IN THE HSG47 GUIDE.
COORDINATE SYSTEM SETTINGS:
SYSTEM - UNITED KINGDOM ZONE - OS NATIONALGRID(OSTN02)
DATUM - ORDNANCE SURVEY GEOID MODEL - (OSGM02)
COORDINATE ORDER - EAST FIRST - NORTH LAST

N

REFERENCE DRAWINGS.

DRAWING No	TITLE

Project Title: Cranwood House

Client: McAllister Group

Discipline:		Scale:	Project Phase:
Topographical Survey & Laser Scanning		NTS	Survey Information
Drawing Originator:		Drawn By:	Approval By:
Cable Tracing Services Limted		DMB	JMB
Drawing No:	Revision:	Drawn Date:	Check Date:
CTS-MC 0129 20-21(3)	B	15-12-20	17-06-21





1m 0 10m 20m

SCALE - 1:200

COMPUTER AIDED DRAWING - AVOID MANUAL MODIFICATION

THIS DRAWING MUST NOT BE SCALED,
ALL DIMENSIONS TO BE CHECKED ON SITE.

DISCLAIMER
The information shown within is given without obligation, or warranty, the accuracy thereof cannot be guaranteed. No liability of any kind whatsoever is accepted by Cable Tracing Services Limited its operatives for any error or omission.
Safe digging practices, in accordance with HS(G)47 must be used to verifiy and establish the actual position of the statuary undertaker's apparatus on site before any mechanical plant is used. It is your responsibility to ensure that this information is provided to all persons either direct labour or contractors. Any error found should be reported immediately to the management before any works are to be carried out.

Notes

This 3D Model has been drawn from point cloud data taken from the inside surfaces of the sewer structures.

ALL MEASUREMENTS ARE APPROXIMATE AND SHOULD BE VERIFIED ON SITE BY FOLLOWING THE SAFE DIGGING PRACTICES SET OUT IN THE HSG47 GUIDE.

COORDINATE SYSTEM SETTINGS:
SYSTEM - UNITED KINGDOM ZONE - OS NATIONALGRID(OSTN02)
DATUM - ORDNANCE SURVEY GEOID MODEL - (OSGM02)
COORDINATE ORDER - EAST FIRST - NORTH LAST

N

REFERENCE DRAWINGS.

DRAWING No	TITLE

Project Title: Cranwood House

Client: McAllister Group


Discipline:	Scale:	Project Phase:
Topographical Survey & Laser Scanning	NTS	Survey Information
Drawing Originator:	Drawn By:	Approval By:
Cable Tracing Services Limted	DMB	JMB

Drawing No:	Revision:	Drawn Date:	Check Date:
CTS-MC 0129 20-21(4)	B	15-12-20	17-06-21


MH3101
Requires Man entry on winch to check sizes and Inverts




MH4102
Requires remedial action to lift. Caution possibility of damaging frame and cover.



MH3104
Requires Man entry on winch to check sizes and Inverts
Caution Bottom run of ladder Broken
Bottom of Chamber needs cleaning




MH4108
Landings



Approx Postions off MH in Gardens,
Access Required to CCTV Downstream

Camera blocked due to reduction in Pipe Size-
150mm to 100mm







COMPUTER AIDED DRAWING - AVOID MANUAL MODIFICATION

THIS DRAWING MUST NOT BE SCALED,
ALL DIMENSIONS TO BE CHECKED ON SITE.

DISCLAIMER
The information shown within is given without obligation, or warranty, the accuracy thereof cannot be guaranteed. No liability of any kind whatsoever is accepted by Cable Tracing Services Limited its operatives for any error or omission.
Safe digging practices, in accordance with HS(G)47 must be used to verifiy and establish the actual position of the statuary undertaker's apparatus on site before any mechanical plant is used. It is your responsibility to ensure that this information is provided to all persons either direct labour or contractors. Any error found should be reported immediately to the management before any works are to be carried out.

Notes

This 3D Model has been drawn from point cloud data taken from the inside surfaces of the sewer structures.

ALL MEASUREMENTS ARE APPROXIMATE AND SHOULD BE VERIFIED ON SITE BY FOLLOWING THE SAFE DIGGING PRACTICES SET OUT IN THE HSG47 GUIDE.

COORDINATE SYSTEM SETTINGS:
SYSTEM - UNITED KINGDOM ZONE - OS NATIONALGRID(OSTN02)
DATUM - ORDNANCE SURVEY GEOID MODEL - (OSGM02)
COORDINATE ORDER - EAST FIRST - NORTH LAST

REFERENCE DRAWINGS.

DRAWING No	TITLE

Project Title: Cranwood House

Client: McAllister Group

Discipline:	Scale:	Project Phase:
Topographical Survey & Laser Scanning	1:250@ A1	Survey Information
Drawing Originator:	**Drawn By:**	**Approval By:**
Cable Tracing Services Limted	AMB	JMB
Drawing No:	**Revision:**	**Drawn Date:** / **Check Date:**
CTS-MC 0129 20-21(5)	C	15-12-20 / 17-06-21