

Mallinson Centre, Bishopswood Road N6 4NY



Tree ID	Common Name	Height (m)	DBH (mm)	Crown Spread (m)	Age Class	Physiological Condition	Structural Condition	Observations	Recommendation	Pr
3928	Sycamore	10	250	5	D	Dead	Fair	Dead tree.	Fell.	6
3929	Mixed species including Silver Birch and Sycamore	12	200	3	OM	Poor	Fair	Dead and dying trees throughout the forest school area.	Fell dead and dying trees.	6
3930	Sycamore	14	300	4	D	Dead	Poor	Dead tree poor condition.	Fell.	3
3931	Crack Willow	8	200	5	M	Good	Poor	Splitting union	Pollard to 4m.	6
3932	Sycamore Group	18	500	10	M	Good	Good	Several Sycamores contacting or close to buildings.	Raise crowns to achieve 2m clearance	6
3933	Common Lime	13	400	7	OM	Good	Fair	Hollow tree, previously reduced.	Reduce to 5m.	6


T3928


T3931


T3932


T3932


T3933