
15 Denewood Road N6 4AQ









T1: Austrian Pine (22m): Reduce by up to 2.5m over driveway and reduce back by up to 1m from the house to reduce the risk of failure as some branches have snapped out recently and as part of regular maintenance