

Materials Schedule for Phase one works to 37 North Road, Haringey

June 2025

Information relevant to applications: HGY/2024/2339 & HGY/2024/2437

Material	New/repair	Material details	Image
1. Slate	Repair, whereby existing original/historic Welsh slate to be salvaged for reuse where capable of reuse New slate where required to replace inferior Spanish slate previously introduced as part of past repair (assume c.2013)	New material as Penrhyn Welsh slate from Welsh Slate to match sizing of original/historic slate Penrhyn® Welsh Slate Roofing - Welsh Slate	
2. Roofing membrane	New roofing membrane replacing modern c.2013 membrane	Breather membrane	-
3. Lead	New lead to be introduced to flat roof, parapet gutters, dormers, verge and ridge introduced replacing damaged leadwork	Code 5 lead ALM Code 5 Lead, Timber & Builders Merchants - Condell	

4. Rainwater goods	New gutter and downpipe to be introduced to rear replacing extant plastic goods.	Alumasc powder coated aluminium rainwater goods (half round range) Heritage Cast Aluminium Gutter & Downpipe Manufacturers	
5. Render	New render to rear elevation	New render as lime	-