


Aylmer Court, Aylmer Road N2 0BU



G8	Common Lime <i>Tilia europaea</i>	18	400 Ave	6	M	P: Good - Normal vitality S: - Restricted access. Unable to fully assess, however no significant defects immediately obvious fro viewpoint	Observations: Linear off site group of 18 mature, near boundary trees. Western canopies overhangs access road by up to circa 2m. Branch ends within 2m from flats, side elevation. Low branches overhang access road. Recommendations: Shorten lateral branches back to a point in-line with the boundary fence. No cuts pruning to be made on the tree side of the boundary
----	--------------------------------------	----	------------	---	---	---	--