



SUBSIDENCE MONITORING

Level Monitoring

Our Ref: 4699

Date of Issue: 27/09/2022

Provider Details

Monitoring Details

Instruction Date:	30/03/2022		
Number of visits	MUFN	Visit Frequency (Wks)	8

Visit Dates (future dates are estimated)

Setup	1	2	3	4	5	6

Client Details

Insurance Co.:	
Client Ref:	212706
Client Name:	Andrew Brindle
Technical Mgr:	
Customer support	
Tel:	
Email:	abrindle@smitherspurslow.com


Risk Address

Occupier:	Miss Watt
Address:	15 Stanhope Gardens
Address:	
Town:	London
County:	
Post Code:	N6 5TT
Contact Name	Miss Watt

Level Monitoring - Site Sketch

Our Ref: 4699

Date of Issue: 27/09/2022



Level Monitoring - Reduced Levels (in metres)

Our Ref:

4699

Date of Issue:

27/09/22

Reading Date	8/4/22	30/5/22	2/8/22	26/9/22								
Point / Reading	1	2	3	4	5	6	7	8	9	10	11	12
1	10.0000	10.0000	10.0000	10.0000								
2	9.8390	9.8390	9.8384	9.8392								
3	10.0086	10.0077	10.0070	10.0076								
4	9.9206	9.9212	9.9193	9.9200								
5	10.1587	10.1578	10.1531	10.1536								
6	10.8727	10.8721	10.8650	10.8653								
7	10.7246	10.7241	10.7177	10.7180								
8	11.0008	11.0000	10.9930	10.9940								
not used												
not used												
not used												
not used												
not used												
not used												
not used												
not used												
Tech Initials	JL	BA	NM	BA								
Level S/N.	523715	522888	523936	521856								



SUBSIDENCE MONITORING

4699

Date of Issue

27/09/22

[illegible]

