

LEVEL MONITORING

for Subsidence Management Services

12 Park Avenue, London, N22 7EX

Client:	Subsidence Management Services
Client Contact:	Chris Sherwin
Claim Number:	4501341229
Client Reference:	IFS-AVI-SUB-21-0091858
Policy Holder:	Ms Krycia Fedorowitz
Report Date:	11 October 2022
Our Ref:	M18690


Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5	6	7	8	9	10
12/06/2022	10.4244	10.3799	10.3269	10.2689	10.6114	10.3757	10.3496	10.4223	10.4079	10.2580
11/08/2022	10.4235	10.3788	10.3267	10.2698	10.6129	10.3750	10.3446	10.4078	10.3861	10.2309
06/10/2022	10.4229	10.3785	10.3265	10.2693	10.6137	10.3747	10.3435	10.4052	10.3834	10.2272
Date	11	12								
12/06/2022	10.1418	10.2272								
11/08/2022	10.1280	10.2182								
06/10/2022	10.1244	10.2156								

Level Monitoring Difference Graphs



The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.





Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

Readings have been made relative to the deep datum. It has an assumed value of 10.0000m. No secondary TBM.