

Photographs taken at Page High, 4 Lymington Avenue, London, N22 6JQ
Existing timber balustrades, windows and dividers to be replaced
Recorded on 11th November January 2022



Photo (1)



Photo (2)



Photo (3)



Photo (4)

Photographs taken at Page High, 4 Lymington Avenue, London, N22 6JQ
Existing timber balustrades, windows and dividers to be replaced
Recorded on 11th November January 2022



Photo (5)



Photo (6)



Photo (7)



Photo (8)

Photographs taken at Page High, 4 Lymington Avenue, London, N22 6JQ
Existing timber balustrades, windows and dividers to be replaced
Recorded on 11th November January 2022



Photo (9)



Photo (10)



Photo (11)



Photo (12)

Photographs taken at Page High, 4 Lymington Avenue, London, N22 6JQ
Existing timber balustrades, windows and dividers to be replaced
Recorded on 11th November January 2022



Photo (13)



Photo (14)




Photo (15)



Photo (16)

Photographs taken at Page High, 4 Lymington Avenue, London, N22 6JQ
Existing timber balustrades, windows and dividers to be replaced
Recorded on 11th November January 2022



Photo (17)



Photo (18)




Photo (19)



Photo (20)

Photographs taken at Page High, 4 Lymington Avenue, London, N22 6JQ
Existing timber balustrades, windows and dividers to be replaced
Recorded on 11th November January 2022



Photo (21)