



Jack Holliday

Keltbray Remediation Ltd
St Andrew's House
Portsmouth Road
Esher
KT10 9TA

t: 02076431000

e: Jack.Holliday@Keltbray.com



i2 Analytical Ltd.
7 Woodshots Meadow,
Croxley Green
Business Park,
Watford,
Herts,
WD18 8YS

t: 01923 225404

f: 01923 237404

e: reception@i2analytical.com

Analytical Report Number : 20-31487

Project / Site name:	Clarendon Road Phase 3	Samples received on:	23/09/2020
Your job number:		Samples instructed on/ Analysis started on:	23/09/2020
Your order number:	S-RE6075/00005	Analysis completed by:	30/09/2020
Report Issue Number:	1	Report issued on:	30/09/2020
Samples Analysed:	4 bulk samples		

Signed: *A. Czerwińska*

Agnieszka Czerwińska
Technical Reviewer (Reporting Team)
For & on behalf of i2 Analytical Ltd.

Standard Geotechnical, Asbestos and Chemical Testing Laboratory located at: ul. Pionierów 39, 41 -711 Ruda Śląska, Poland.

Accredited tests are defined within the report, opinions and interpretations expressed herein are outside the scope of accreditation.

Standard sample disposal times, unless otherwise agreed with the laboratory, are :

soils - 4 weeks from reporting
leachates - 2 weeks from reporting
waters - 2 weeks from reporting
asbestos - 6 months from reporting

Excel copies of reports are only valid when accompanied by this PDF certificate.

Any assessments of compliance with specifications are based on actual analytical results with no contribution from uncertainty of measurement.
Application of uncertainty of measurement would provide a range within which the true result lies.
An estimate of measurement uncertainty can be provided on request.



Analytical Report Number: 20-31487
Project / Site name: Clarendon Road Phase 3

Your Order No: S-RE6075/00005

Lab Sample Number				1627909	1627910	1627911	1627912
Sample Reference				ASB1	ASB2	ASB3	ASB4
Sample Number				None Supplied	None Supplied	None Supplied	None Supplied
Depth (m)				None Supplied	None Supplied	None Supplied	None Supplied
Date Sampled				22/09/2020	22/09/2020	22/09/2020	22/09/2020
Time Taken				None Supplied	None Supplied	None Supplied	None Supplied
Analytical Parameter (Bulk Analysis)				Units	Limit of detection	Accreditation Status	

Asbestos Identification	Type	N/A	ISO 17025	No Asbestos Detected	Chrysotile Hard/Cement Type Material	Chrysotile Hard/Cement Type Material	Chrysotile Hard/Cement Type Material
-------------------------	------	-----	-----------	----------------------	--------------------------------------	--------------------------------------	--------------------------------------

U/S = Unsuitable Sample I/S = Insufficient Sample



Analytical Report Number : 20-31487

Project / Site name: Clarendon Road Phase 3

Water matrix abbreviations: Surface Water (SW) Potable Water (PW) Ground Water (GW)

Analytical Test Name	Analytical Method Description	Analytical Method Reference	Method number	Wet / Dry Analysis	Accreditation Status
Asbestos identification in Bults	Asbestos Identification in bulk material with the use of polarised light microscopy in conjunction with disperion staining techniques.	In house method based on HSG 248	A001-PL	W	ISO 17025

For method numbers ending in 'UK' analysis have been carried out in our laboratory in the United Kingdom.

For method numbers ending in 'PL' analysis have been carried out in our laboratory in Poland.

Soil analytical results are expressed on a dry weight basis. Where analysis is carried out on as-received the results obtained are multiplied by a moisture correction factor that is determined gravimetrically using the moisture content which is carried out at a maximum of 30oC.