


GEOSHIELD Verification Report


ADDITIONAL PHOTOGRAPHS



Overview of verified area



Pick and probe and sealed lap



Vertically applied membrane and

sealed lap joint



Overview of sealed pile heads



Gridline/Plot Sign off



GEOSHIELD Verification Report



VERIFICATION SUMMARY

Report 001 is for Block D1 - Core - Lower

All works verified visually and using a pick and probe method. Pipe heads sealed

with good coverage of liquid membrane and double sided tape, allowing

Pudlo GP Ultra+ Gas Barrier to be sealed. Welded lap joints also installed to

very high standard. All to manufacturers specification.

Passed and verified in accordance with BS8485:2019 and CIRIA 735.

GEOSHIELD SIGNATURE:

DATE: 12th November 2020