

GEOSHIELD Verification Report

BGA
British Geomembrane Association



VERIFICATION ITEM ONE

LOCATION/GRID LINE: Block D1 - Core - Lower

NOTES: Pudlo Liquid gas barrier has been applied to the pile heads

and a good coverage has been achieved. Double sided tape has then been installed

around all pipe heads to seal Pudlo GP Ultra+ Gas Barrier to the pile heads. Pick and

probe tests carried out to ensure continuous seal was created.



Overview photos of sealed and completed pile heads with double sided tape applied.

To manufacturers specification.

GEOSHIELD Verification Report

VERIFICATION ITEM ONE



Above photo) pick and probe tests were carried out on all sealed and completed pile heads to ensure a continuous seal had been created.



GEOSHIELD Verification Report




VERIFICATION ITEM TWO

LOCATION/GRID LINE: Block D1 - Core - Lower

NOTES: Sealed Lap Joints

Pudlo GP Ultra+ Gas Barrier has been installed across the verified area and overlaps has been created. They have been sealed using a leister to manufacturers specification.



The above photos show overviews of the verified area, and the red arrows shows the welded lap joints. All laps have been sealed to a high standard and to manufacturers specification.