

GEOSHIELD Verification Report

ADDITIONAL PHOTOGRAPHS



Last section of installation witnessed




Pile heads fully sealed



Pile heads fully sealed to Pudlo

GP Ultra +



Overview of verified area



Gridline/Plot Sign off



GEOSHIELD Verification Report



VERIFICATION SUMMARY

Report 002 is for Block D1 - Core - Middle and Upper and Pump Chamber Base.

All works visually inspected and tested with pick and probe. Installation has

been carried out as per the design to a high standard. All pile heads are fully

sealed and linked to Pudlo GP Ultra+. Joints hot welded, visually inspected and

tested with pick and probe and no faults found.

Excellent install.

Passed and verified in accordance with BS8485:2019 and CIRIA 735.

GEOSHIELD SIGNATURE:

DATE: 12th November 2020