



GEOSHIELD

Verification Report



PROJECT REFERENCE:

GEO101436

REPORT NUMBER:

001

PROJECT:

GCL - Clarendon Road PHASE 3

PROJECT ADDRESS:

Clarendon Road

Hornsey

N8 0JU

MEMBRANE SPECIFICATION:

Gas membrane to specification BS8485 2015

Installed to CIRIA 735

Pudlo GP Ultra+ Gas Barrier

Pudlo GP Ultra Tape

Pudlo GP Ultra EXT Tape

Pudlo Liquid Gas Barrier



GEOSHIELD
Verification
PLAN



SPECIFICATION:

INFORMATION INCLUDED:

Material specification technical data sheets

5192204/P3_RemStrat Rev0.4

W257-PUD-D1-00-DR-S-02-1000

W257-PUD-D2-00-DR-S-02-1001

W257-PUD-D3-FN-DR-S-02-1002

W257-PUD-D3-XX-DR-S-02-1005

W257-PUD-D3-XX-DR-S-05-1000

W257-PUD-D4-00-DR-S-01-1006

W257-PUD-D4-BL-DR-S-02-1003

W257-PUD-DD-XX-DR-S-03-0001 to W257-PUD-DD-XX-DR-S-03-0024

W257-PUD-DD-XX-SK-S-03-0001 to W257-PUD-DD-XX-SK-S-03-0003

Information brought forward from the Pre Verification Plan. Any alterations to the originaally submitted design should be made aware to Geoshield



GEOSHIELD Verification Report



VERIFICATION OFFICER: Finlay Todd

VERIFICATION COMPANY: GeoShield Limited

Icon Business Park, 4100 Park Approach

Thorpe Park, LEEDS

West Yorkshire

LS15 8GB

CONTACT NUMBER: 07502343063

EMAIL ADDRESS: Ftodd@Geoshield.co.uk

ORDER NUMBER:

PER VISIT: YES:



NO:



PROJECT: YES:



NO:





GEOSHIELD

Verification Report



CLIENT DETAILS

CLIENT CONTACT:	Rohallah De Sousa
CONTACTS ROLE:	Ground Construction Ltd
MOBILE PHONE:	02082387000
EMAIL ADDRESS:	RohallahDeSousa@GroundConstruction.com



CLIENT CONTACT:	
CONTACTS ROLE:	
MOBILE PHONE:	
EMAIL ADDRESS	
NOTES:	
NOTES:	
NOTES:	



GEOSHIELD Verification Report



APPLICATION TEAM LEADERS

APPLICATOR NAME:

COMPANY:

APPLICATOR TEL:

APPLICATOR EMAIL:

APPLICATOR NAME:

COMPANY:

APPLICATOR TEL:

APPLICATOR EMAIL:

NOTES:

NOTES:

NOTES:

NOTES:



GEOSHIELD Verification Report



AREA SURVEYED: Block D1 - Core - Lower

SITE CONDITIONS:

WEATHER: Clear

TEMPERATURE: 9c

MEMBRANE TEMPERATURE: N/A

RELATIVE HUMIDITY:

TIME: 11:00-12:45


REPORT NUMBER: 001

DATE: 10th November 2020

ACCOMPANIED: Ermal - GCL Site Engineer

GEOSHIELD Verification Report

VERIFICATION LAYOUT



Block D1 - Core - Lower

Highlighted above




GEOSHIELD Verification Report



OVERVIEW PHOTOGRAPHS



Overview of D1 Core - Lower





GEOSHIELD Verification Report



OVERVIEW PHOTOGRAPHS



Overview of D1 Core - Base

