

GEOSHIELD Verification Report

ADDITIONAL PHOTOGRAPHS




Tric trac spacers to vertical




Pump chamber base tested with

pick and probe



Overview of middle section



Pile heads all sealed