




GEOSHIELD Verification Report



OVERVIEW PHOTOGRAPHS



Pump Chamber Base





GEOSHIELD Verification Report



LIMITATIONS

SURVEY AREA: Block D1 - Core - Middle and Upper

RESTRICTIONS AND LIMITATIONS: All areas accessible for inspection.



GEOSHIELD Verification Report

BGA
British Geomembrane Association



VERIFICATION ITEM ONE

LOCATION/GRID LINE: Block D1 - Core - Middle and Upper

NOTES: Pile heads sealed to high standard. All works visually

inspected and tested with pick and probe to ensure good bond achieved. Double sided

tape installed around all pile heads to seal to Pudlo GP Ultra + Gas Barrier. Good

covering of Pudlo Liquid Gas Barrier to all pile heads.



1. Photo evidence

2. Photo evidence