

Grid Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny/rainy Spells	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G11-S		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-G12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
-------------------	---------------	--------------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny/rainy Spells	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G11		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.2			
Sample ID:			
VS-G12			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	19.06.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny Spells	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G11-W		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (ppm):			
0			
Sample ID:			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny/rainy Spells	Date and Time:	06/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G12		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.2			
Sample ID:			
VS-G12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	06/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny Spells	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G12-W		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (ppm):			
0			
Sample ID:			
VS-G12-W			
Comments:			
N/A			
Photo(s):			



Sig		Date:	19.06.20
-----	--	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G13		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-G13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny Spells	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	G13-N		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (ppm):			
0			
Sample ID:			
VS-G13-N			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Rainy showers	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	H11		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (ppm):			
0			
Sample ID:			
VS-H11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton		
------------	---------------	--	--

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	H12		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.4			
Sample ID:			
VS-H12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	04/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	H13-N		
General Description of Material:			
Brown and grey gravelly London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-H13-N			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	04/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	04/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	H13		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-H13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	04/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	24/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-7		
General Description of Material:			
Brown slightly gravelly natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
5			
Sample ID:			
VS-17			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	24/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-8		
General Description of Material:			
Brown slightly gravelly natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
4			
Sample ID:			
VS-18			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	24/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-8		
General Description of Material:			
Brown slightly gravelly natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
6			
Sample ID:			
VS-18			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	24/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-9		
General Description of Material:			
Brown, slightly gravelly, natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.3			
Sample ID:			
VS-19			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I10		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.5			
Sample ID:			
VS-I10			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I11		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.1			
Sample ID:			
VS-I11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	07/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I12		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.2			
Sample ID:			
VS-I12			
Comments:			
N/A			
Photo(s):			



Signature:			07/09/2020
------------	--	--	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I13		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.4			
Sample ID:			
VS-I13			
Comments:			
N/A			
Photo(s):			
			
Signature:			07/09/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I13-N		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.5			
Sample ID:			
VS-I13-N			
Comments:			
N/A			
Photo(s):			
			
Signature:			07/09/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	24/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-7		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
5			
Sample ID:			
VS-J7			
Comments:			
N/A			
Photo(s):			

Signature:	Alix Hamilton	Date:	24/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	24/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-8		
General Description of Material:			
Brown slightly gravelly natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
6			
Sample ID:			
VS-J8			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	19.06.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	24/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-8-E		
General Description of Material:			
Brown slightly gravelly natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
4			
Sample ID:			
VS-J8 E			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	19.06.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-9		
General Description of Material:			
Brown slightly gravelly natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
1.5			
Sample ID:			
VS-J9			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	07/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	07/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-10		
General Description of Material:			
Stiff brown clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
1.1			
Sample ID:			
VS-J10			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	07/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	11/08/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-11		
General Description of Material:			
Dark brown, gravelly natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.4			
Sample ID:			
VS-J11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	11/08/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.2			
Sample ID:			
VS-J12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	11/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	02/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
3			
Sample ID:			
VS-J13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	02/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	18/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K-7		
General Description of Material:			
Brown gravelly natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
2			
Sample ID:			
VS-K7			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	18/09/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	21/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K-8		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
1			
Sample ID:			
VS-K8			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	21/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	25/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K-9		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
1			
Sample ID:			
VS-K9			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	25/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K10		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K10			
Comments:			
N/A			
Photo(s):			



Signature:		19.06.20
------------	--	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K11			
Comments:			
N/A			
Photo(s):			
			
Signature:			19.06.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K12			
Comments:			
N/A			
Photo(s):			
			
Signature:			19.06.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K13		
General Description of Material:			
Brown gravelly Made Ground			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K13			
Comments:			
N/A			
Photo(s):			



Signature:		19.06.20
------------	--	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	23/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L7		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.1			
Sample ID:			
VS-L7			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	23/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L8		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
2			
Sample ID:			
VS-L8			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton		Date: 21/09/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	23/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L9		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L9			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	23/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L10		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L10			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	12/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M10		
General Description of Material: Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory signs of contamination			
VOC PID analysis (PPM): 0			
Sample ID: VS-M10			
Comments: N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	12/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	28/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	28/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N10		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N10			
Comments:			
N/A			
Photo(s):			



Signature:		08/07/2020
------------	--	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N11		
General Description of Material:			
Backfilled brown slightly gravekly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N11			
Comments:			
N/A			
Photo(s):			



Sign

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O10		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination.			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O10			
Comments:			
N/A			
Photo(s):			



Signature:				7/2020
------------	--	--	--	--------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O11		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VP-O11			
Comments:			
N/A			
Photo(s):			



Signature:			7/2020
------------	--	--	--------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O12		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O12			
Comments:			
N/A			
Photo(s):			



Signature:		7/2020
------------	--	--------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-013			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	19.06.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-013			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P-4		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P4			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	21/07/2020 00:00
-------------------	---------------	--------------	------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P5		
General Description of Material:			
Brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P5			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	21/07/2020 00:00
------------	---------------	-------	------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P6		
General Description of Material:			
Brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P6			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	21/07/2020 00:00
------------	---------------	-------	------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P7		
General Description of Material:			
Brown natural CLAY.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P7			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	21/07/2020 00:00
------------	---------------	-------	------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P8		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
Comments:			
N/A			
Photo(s):			



Signature:			2020
------------	--	--	------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P9		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P9			
Comments:			
N/A			
Photo(s):			



Signature:			020
------------	--	--	-----

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P10		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P10			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	08/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P11		
General Description of Material:			
Backfilled brown slightly gravekly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P11			
Comments:			
N/A			
Photo(s):			



Signature:		020
------------	--	-----

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P12		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	08/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P13			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	20/07/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P13 N		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P13 N			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q5		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q5			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	08/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q6		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q6			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	08/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q7		
General Description of Material:			
Brown gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q7			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton		Date: 08/07/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q8		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q8			
Comments:			
N/A			
Photo(s):			



Signature:			7/2020
------------	--	--	--------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q9		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q9			
Comments:			
N/A			
Photo(s):			



Signature:			/2020
------------	--	--	-------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q10		
General Description of Material:			
Backfilled brown slightly gravekly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
Backfilled brown slightly gravekly clayey Made Ground.			
Comments:			
N/A			
Photo(s):			



Signature:			2020
------------	--	--	------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q11		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q11			
Comments:			
N/A			
Photo(s):			
			
Signature:			07/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q12		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q12			
Comments:			
N/A			
Photo(s):			



Signature:			7/2020
------------	--	--	--------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q13 N		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q13 N			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R6		
General Description of Material:			
Gravelly, clayey Made Ground with wood chippings.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R6			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	08/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R7		
General Description of Material:			
Gravelly, clayey Made Ground with wood chippings.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R7			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	08/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R8		
General Description of Material:			
Brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R8			
Comments:			
N/A			
Photo(s):			



Signature:			
------------	--	--	--

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R9		
General Description of Material:			
Brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
Backfilled brown slightly gravelly clayey Made Ground.			
Comments:			
N/A			
Photo(s):			



Signature:			2020
------------	--	--	------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R10		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R10			
Comments:			
N/A			
Photo(s):			



Signature:		/2020
------------	--	-------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	08/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R11		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R11			
Comments:			
N/A			
Photo(s):			



Signature:			
------------	--	--	--

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R13 N		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S8		
General Description of Material:			
Gravelly, clayey Made Ground with wood chippings.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-S8			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S9		
General Description of Material:			
Gravelly, clayey Made Ground with wood chippings.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-S9			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S10		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-S10			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-S11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-S12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S13 N		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-S13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	S13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-S13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	T10		
General Description of Material:			
Gravelly, clayey Made Ground with wood chippings.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-T10			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	T11		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-T11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	T12		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-T12			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	T13		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-T13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	T13 N		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-T13 N			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	20/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-3		
General Description of Material: Brown gravelly MG			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory signs of contamination			
VOC PID analysis (PPM): 0			
Sample ID: VS-I3			
Comments: N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	20/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-3		
General Description of Material:			
Brown gravelly MG			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-13			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	20/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-4		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
47			
Sample ID:			
VS-14			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	20/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-4		
General Description of Material:			
Brown gravelly natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-I4			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	20/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-5		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-15			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	20/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I-6		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-I6			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J3		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-J3			
Comments:			
N/A			
Photo(s):			



Signature:		19.06.20
------------	--	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J4		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
43			
Sample ID:			
VS-J4			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	19.06.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-5		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
15			
Sample ID:			
VS-J5			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	07/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	07/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J-6		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
11			
Sample ID:			
VS-J6			
Comments:			
N/A			
Photo(s):			
			
Signature:			07/09/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K3		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K3			
Comments:			
N/A			
Photo(s):			



Signature:			
------------	--	--	--

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K4		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K4			
Comments:			
N/A			
Photo(s):			



Signature:		06.20
------------	--	-------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	08/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K-5		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K5			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	08/09/2020 00:00
------------	---------------	-------	------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	08/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K-6		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K6			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	08/09/2020 00:00
------------	---------------	-------	------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L3		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L3			
Comments:			
N/A			
Photo(s):			
			
Signature:			

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	01/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L4		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (%):			
0			
Sample ID:			
VS-L4			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	01/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	09/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L5		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0.2			
Sample ID:			
VS-L3			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	09/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	09/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L6		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (%):			
0			
Sample ID:			
VS-L4			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	01/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M3		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M3			
Comments:			
N/A			
Photo(s):			



Signature:		19.06.20
------------	--	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M4		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M4			
Comments:			
N/A			
Photo(s):			
			
Signature:			.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	13/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M5		
General Description of Material:			
Sandy gravelly clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M5			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	13/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	13/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M6		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M6			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	13/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	09/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M7		
General Description of Material: Brown gravelly sandy CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory signs of contamination			
VOC PID analysis (PPM): 0			
Sample ID: VS-M7			
Comments: N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	09/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	09/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M8		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M8			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	09/09/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	20/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M9		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N-3		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N3			
Comments:			
N/A			
Photo(s):			



Signature:	A	Date:	20/07/2020
------------	---	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N-4		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q4			
Comments:			
N/A			
Photo(s):			



Signature:	Alix	20/07/2020
------------	------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	13/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N5		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M3			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	13/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	13/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N6		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M4			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	13/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	02/09/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N7		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M11			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	02/09/2020
-------------------	---------------	--------------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	11/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N8		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N3			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	11/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N9		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N9			
Comments:			
N/A			
Photo(s):			



Signa

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O-3		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination (blue spray paint in photo).			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O3			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O-4		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O4			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	20/07/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	13/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O5		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O5			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	13/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O6		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O6			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	19.06.20
------------	---------------	-------	----------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	10/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O7		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-07			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	10/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O8		
General Description of Material:			
Backfilled brown slightly gravelly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O8			
Comments:			
N/A			
Photo(s):			



Signature:			7/2020
------------	--	--	--------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/04/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P8		
General Description of Material:			
Backfilled brown slightly gravekly clayey Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-09			
Comments:			
N/A			
Photo(s):			



Signature:		/2020
------------	--	-------

Grid Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	10		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-10			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
-------------------	---------------	--------------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I1		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-I1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I2-W		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-I2-W			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	I2		
General Description of Material:			
Brown natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-I2			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J0		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-J0			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J0		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-J0-S			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J1		
General Description of Material:			
Type one fill material. Grey slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-J1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	25/08/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	J2		
General Description of Material:			
Brown natural CLAY			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N0			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	25/08/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K0		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K0			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K1		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-K1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	K2		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PMM):			
0			
Sample ID:			
VS-K2			
Comments:			
N/A			
Photo(s):			
			
Signature:			

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L0		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L0			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	03/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L1		
General Description of Material:			
Type one fill material. Pink slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L1			
Comments:			
N/A			
Photo(s):			




Signature:	Alix Hamilton	Date:	03/07/2020 00:00
------------	---------------	-------	------------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	L2		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-L2			
Comments:			
N/A			
Photo(s):			



Signature:			9.06.20
------------	--	--	---------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M0		
General Description of Material:			
Type one fill material. Grey slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M0			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M1		
General Description of Material:			
Type one fill material. Grey slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	19/06/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M2		
General Description of Material:			
Brown and grey mottled London Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-M2			
Comments:			
N/A			
Photo(s):			
			
Signature:			19.06.20

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	03/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	NO		
General Description of Material:			
Type one fill material. Grey slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-NO			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	03/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N1		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	N-2		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-N2			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	M1		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-00			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O-1		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	21/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	O-2		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-O2			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P2		
General Description of Material:			
Brown natural Clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P2			
Comments:			
N/A			
Photo(s):			
			
Signature:	Alix Hamilton	Date:	31/07/2020

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P-1		
General Description of Material:			
Type one fill material. Grey slightly sandy GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	P0		
General Description of Material:			
Brown gravelly CLAY.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-P0			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q-2		
General Description of Material:			
Brown clayey gravelly Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q-2			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q-1		
General Description of Material:			
Type one fill material. Light grey slightly sandy, slightly silty GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q-1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	Q0		
General Description of Material:			
Type one fill material. Light grey slightly sandy, slightly silty GRAVEL. Gravels angular to subangular of concrete, limestone and flint.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-Q0			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R-2		
General Description of Material:			
Brown gravelly Made Ground			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R-2			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------

Grid Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	31/07/2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Validation Grid:	R-1		
General Description of Material:			
Brown granular Made Ground			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (PPM):			
0			
Sample ID:			
VS-R-1			
Comments:			
N/A			
Photo(s):			



Signature:	Alix Hamilton	Date:	31/07/2020
------------	---------------	-------	------------