

Stockpile Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast /sunny spells/occ showers	Date and Time:	12/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-Knotweed		
Stockpile volume (m3) *1 sample per 250m3	6		
General Description of Material: topsoil and made ground removed during knotweed excavation/removal.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory signs of contamination			
VOC PID analysis (ppm): 0			
Sample ID: sp-knotweed			
Comments: Topsoil from the knotweed excavation as supervised by specialist. Stored in lined skip for disposal.			
Photo(s):			



Signature:	Alix Hamilton	Date:	11.06.20
------------	---------------	-------	----------

Stockpile Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast /sunny spells/occ showers	Date and Time:	12/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-sludge		
Stockpile volume (m3) *1 sample per 250m3	144		
General Description of Material:			
Dried and turned black sludge and brick screened from trench hotpot in J.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
Dried and turned black sludge and brick screened from trench hotpot in J.			
VOC PID analysis (ppm):			
854			
Sample ID:			
Sp-sludge			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	11.06.20
------------	---------------	-------	----------

Stockpile Validation Inspection Form			
Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	16/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-Asbestos		
Stockpile volume (m3) *1 sample per 250m3	22		
General Description of Material:			
Dried and turned black sludge and brick screened from trench hotpot in J.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
Dried and turned black sludge and brick screened from trench hotpot in J.			
VOC PID analysis (ppm):			
0.1			
Sample ID:			
Sp-sludge			
Comments:			
Photo(s):			

Signature:	Alix Hamilton	Date:	16/06/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	05.06.2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP0		
Stockpile volume (m3) *1 sample per 250m3	400m3, SP0 sample 1 and sample 2		
General Description of Material: Crushed concrete and brick fines.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory signs of contamination			
VOC PID analysis (ppm): 0			
Sample ID: SP0			
Comments: Crushed concrete and fines from central wall and concrete slab- used in temporary ramp into GH3 and between high and low level			
Photo(s):			



Signature:	Alix Hamilton	Date:	08.06.20
-------------------	---------------	--------------	----------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Sunny	Date and Time:	05.06.2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP1		
Stockpile volume (m3) *1 sample per 250m3	231		
General Description of Material:			
Light brown gravelly made ground with flint gravels and broken brick and concrete fragments. Screened and stockpiled adjacent to GH3. End destination TBC			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (ppm):			
0			
Sample ID:			
SP1, SP1 (2), (SP2, SP3 combined).			
Comments:			
combined SP1, SP2, SP3 from previous works adjacent to the marketing suite.			
Photo(s):			



Signature:	Alix Hamilton	Date:	
-------------------	---------------	--------------	--

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	overcast/sunny spells	Date and Time:	12/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP004		
Stockpile volume (m3) *1 sample per 250m3	480		
General Description of Material:			
Type 1 site won material from car park excavation			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory signs of contamination			
VOC PID analysis (ppm):			
0			
Sample ID:			
sp-004 x3			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	12/06/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast /sunny spells	Date and Time:	12/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP005		
Stockpile volume (m3) *1 sample per 250m3	320		
General Description of Material: Crushed and screened concrete			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory signs of contamination			
VOC PID analysis (ppm): 0			
Sample ID: sp-005 x2			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	
-------------------	---------------	--------------	--

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast /sunny spells	Date and Time:	12/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP006		
Stockpile volume (m3) *1 sample per 250m3	233		
General Description of Material:			
Ashy sandy gravelly made ground. Gravells of flint, slag, brick and concrete.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
Black in colour with moderate burnt and gas works odour.			
VOC PID analysis (ppm):			
10.7			
Sample ID:			
SP-006 and Q12 1.5m			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	16/06/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	rain showers	Date and Time:	16/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-pocket park		
Stockpile volume (m3) *1 sample per 250m3	246		
General Description of Material: screened fill material consisting of sandy Type 1, brick fragments, flint gravels.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory signs of contamination			
VOC PID analysis (ppm): 0			
Sample ID: sp-pocket park/			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17.06.20
-------------------	---------------	--------------	----------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast /sunny spells	Date and Time:	19/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP008		
Stockpile volume (m3) *1 sample per 250m3	134		
General Description of Material:			
Clay scrape from Car Park excavation to FL.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
Slight gas works odour			
VOC PID analysis (ppm):			
0			
Sample ID:			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	18/06/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Rain showers	Date and Time:	16/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP009		
Stockpile volume (m3) *1 sample per 250m3	550		
General Description of Material:			
Crushed and screened ashy made ground from the pocket park. Consisting of sandy ashy gravelly made ground. Gravells of flint, brick fragments and concrete.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No odour, visual black ashy made ground with some tarmac.			
VOC PID analysis (ppm):			
0.3			
Sample ID:			
SP-pocket park 1, SP-pocket park 2			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17.06.2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP010		
Stockpile volume (m3) *1 sample per 250m3	495		
General Description of Material: Brown slightly gravelly topsoil from top 0-0.0m Q/R/S 13-11.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory evidence of contamination.			
VOC PID analysis (ppm): SP-010			
Sample ID:			
Comments: brown organic, sandy, gravelly topsoil 0.0-0.5m			
Photo(s):			



Signature:	Alix Hamilton	Date:	17.06.2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP011		
Stockpile volume (m3) *1 sample per 250m3	612		
General Description of Material:			
Soft brown natural CLAY from 0.5-3mbgl Q/R/S 13-11.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
No visual or olfactory evidence of contamination.			
VOC PID analysis (ppm):			
0.3			
Sample ID:			
SP-011.1-6			
Comments:			
clean brown clay 0.5-3mbgl			
Photo(s):			



Signature:	Alix Hamilton	Date:	
-------------------	---------------	--------------	--

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	25/06/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP012		
Stockpile volume (m3) *1 sample per 250m3	217		
General Description of Material: mottled black /brown reworked clay			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: No visual or olfactory evidence of contamination.			
VOC PID analysis (ppm): 0			
Sample ID: SP-012			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	25/06/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP014		
Stockpile volume (m3) *1 sample per 250m3	Estimated 220m3		
General Description of Material: Crushed concrete combined with SP022			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0			
Sample ID: SP-014			
Comments: Crushed hardcore (concrete and brick)			
Photo(s):			



Signature:	Alix Hamilton	Date:	16/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	23/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP015		
Stockpile volume (m3) *1 sample per 250m3	85.6		
General Description of Material:			
Dark grey gravelly MG with full bricks. Bricks screend and crushed and rescreened into the stockpile.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
slight gas works odour and blackish brown clay constituent.			
VOC PID analysis (ppm):			
0			
Sample ID:			
SP-015			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	16/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	24/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP016		
Stockpile volume (m3) *1 sample per 250m3	243		
General Description of Material: type 1 gravelly fill material with clay pockets and whole bricks			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: N/A			
VOC PID analysis (ppm): 0			
Sample ID: SP-016			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	24/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	02/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP017		
Stockpile volume (m3) *1 sample per 250m3	10		
General Description of Material: ashy black gravelly MG from hotspot excavation in Q/-2			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: Ashy Made Ground with slight fuel odour.			
VOC PID analysis (ppm): 0			
Sample ID: SP-017			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	02/07/2020 00:00
-------------------	---------------	--------------	------------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	10/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP018		
Stockpile volume (m3) *1 sample per 250m3	203.2		
General Description of Material: N/O2/3 Brown gravelly MG with brick and flint. High organic content			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: N/A			
VOC PID analysis (ppm): 0			
Sample ID: SP-018			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	10/07/2020
------------	---------------	-------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	10/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP019		
Stockpile volume (m3) *1 sample per 250m3	10/11/1900		
General Description of Material: Crushed concrete from GH3 wall			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
VOC PID analysis (ppm): 0			
Sample ID: SP-019			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	10/07/2020
------------	---------------	-------	------------

Stockpile Validation Inspection Form


Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	20/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP020		
Stockpile volume (m3) *1 sample per 250m3	292.5		
General Description of Material: black ashy gravelly clay. Moderate GW odour			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: Black ashy material.			
VOC PID analysis (ppm): 0.1			
Sample ID: SP-020 (1) [1560694], SP020 (2)[1566874], SP-020(3) [TBC] , SP-020(4) [TBC] .			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	16/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP021		
Stockpile volume (m3) *1 sample per 250m3	178		
General Description of Material: Pink Type 1 fill material. 0.15m-0.7m grid squares JKLM 13-11.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0			
Sample ID: SP-021			
Comments: No evidence of contamination olfactory or visual.			
Photo(s):			



Signature:	Alix Hamilton	Date:	20/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP022		
Stockpile volume (m3) *1 sample per 250m3	3361		
General Description of Material: crushed concrete from the gasholder wall in GH3.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0			
Sample ID: SP-022			
Comments: No evidence of contamination olfactory or visual.			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	sunny	Date and Time:	22/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP023		
Stockpile volume (m3) *1 sample per 250m3	224.5		
General Description of Material: Black wet gravelly made ground with brick, wood and gravels. Monderate to strong gas works odour. Gravels are angular to sub rounded of flint, brick and concrete.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: Black in colour and gas works odour. PID reading of			
VOC PID analysis (ppm): 12			
Sample ID: SP-023			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	23/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast	Date and Time:	30/08/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP021		
Stockpile volume (m3) *1 sample per 250m3	407.2		
General Description of Material:			
Blackish brown granular Made Ground with moderate gas works odour.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
n/a			
VOC PID analysis (ppm):			
1.8-12ppm			
Sample ID:			
SP-024 (1-3)			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	30/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast.	Date and Time:	24/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP025		
Stockpile volume (m3) *1 sample per 250m3	182.7		
General Description of Material: Stiff brown CLAY with slightly gravelly lenses of orangey yellow SAND.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0			
Sample ID: SP-025			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	24/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	Overcast, rainy showers	Date and Time:	27/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP026		
Stockpile volume (m3) *1 sample per 250m3	404		
General Description of Material:			
Brown gravelly sandy MG. Brick and concrete gravels from grid squares N, O, P - 5			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
n/a			
VOC PID analysis (ppm):			
0			
Sample ID:			
SP-026 (4)			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	27/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	clear and sunny	Date and Time:	03/08/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP027		
Stockpile volume (m3) *1 sample per 250m3	68		
General Description of Material:			
Type one, brown gravelly fill material with clay pockets.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
n/a			
VOC PID analysis (ppm):			
0			
Sample ID:			
SP-027			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	03/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	clear and sunny	Date and Time:	28/07/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-028		
Stockpile volume (m3) *1 sample per 250m3	686		
General Description of Material: light orangey brown stiff CLAY mixed with SAND and Gravel			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0			
Sample ID: SP-028 (1-3)			
Comments: stockpiled and rolled into GH1			
Photo(s):			



Signature:	Alix Hamilton	Date:	28/07/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	clear and sunny	Date and Time:	17/08/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-029		
Stockpile volume (m3) *1 sample per 250m3	150		
General Description of Material:			
Screened brick fill material from hotspot trench dig in J			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
n/a			
VOC PID analysis (ppm):			
2			
Sample ID:			
SP-029			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	clear and sunny	Date and Time:	17/08/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-030		
Stockpile volume (m3) *1 sample per 250m3	200		
General Description of Material: Dark greyish brown, granular Made Ground.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: Black ashy colour and moderate gas works odour.			
VOC PID analysis (ppm): 2.2			
Sample ID: SP-30			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	clear and sunny	Date and Time:	17/08/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-031		
Stockpile volume (m3) *1 sample per 250m3	156		
General Description of Material: Brown, natural stiff to firm London Clay.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0			
Sample ID: SP-31			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:			
Stockpile volume (m3) *1 sample per 250m3	157		
General Description of Material: Dark brown gravelly clay from J5/6			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: Moderately strong gas works odour.			
VOC PID analysis (ppm): 14			
Sample ID:			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	
------------	---------------	-------	--

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	01/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-033		
Stockpile volume (m3) *1 sample per 250m3	124		
General Description of Material: Type one site won material from J5/6			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: N/A			
VOC PID analysis (ppm): 0			
Sample ID: Sp-033			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	01/09/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-034		
Stockpile volume (m3) *1 sample per 250m3	219		
General Description of Material: Black stained gravelly clay from J/K/L10 and 11.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 1.4			
Sample ID: sp-034			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	
-------------------	---------------	--------------	--

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:		Date and Time:	01/09/2020 00:00
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	sp-035		
Stockpile volume (m3) *1 sample per 250m3	146		
General Description of Material: Brown granular soil from J5/6			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0			
Sample ID: SP-035(2)			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	sunny/overcast	Date and Time:	02.09.2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-036		
Stockpile volume (m3) *1 sample per 250m3	143		
General Description of Material: greyish brown gravelly MADE GROUND. Consisting of a mixed type one and brick made ground screened material from J5/6 below hardstanding.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0.4			
Sample ID: SP-036			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	sunny/overcast	Date and Time:	02.09.2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-037		
Stockpile volume (m3) *1 sample per 250m3	x3 combined piles:218, 185,126m3		
General Description of Material:			
Clay from J6 and J5, turned, stabilised and stockpiled in situ.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
n/a			
VOC PID analysis (ppm):			
2-5ppm			
Sample ID:			
SP-037			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	sunny/overcast	Date and Time:	02.09.2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-038		
Stockpile volume (m3) *1 sample per 250m3	1677		
General Description of Material: Imported 6F5 material from SRC.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: n/a			
VOC PID analysis (ppm): 0			
Sample ID: SP-038			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	sunny/overcast	Date and Time:	02.09.2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-039		
Stockpile volume (m3) *1 sample per 250m3	530		
General Description of Material:			
Clay pile arisings			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.:			
n/a			
VOC PID analysis (ppm):			
0			
Sample ID:			
SP-039			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------

Stockpile Validation Inspection Form

Site: Clarendon Road Phase 3		Job No: 6075	
Weather Conditions:	sunny/overcast	Date and Time:	02.09.2020
Name of Inspecting Party:	Alix Hamilton		
Company:	Keltbray Remediation		
Nature of Inspection:	Validation		
Stockpile ID:	SP-040		
Stockpile volume (m3) *1 sample per 250m3	171		
General Description of Material: greyish brown gravelly MADE GROUND. Consisting of a mixed type one and brick made ground screened material from J5/6 below hardstanding.			
Visual Evidence of potential contaminants e.g. oily residues, asbestos, etc.: 0			
VOC PID analysis (ppm):			
Sample ID: SP-040			
Comments:			
Photo(s):			



Signature:	Alix Hamilton	Date:	17/08/2020
-------------------	---------------	--------------	------------