


LEVEL MONITORING - RELATIVE SURVEY READINGS

Provider Details			Client Details			Risk Address		
Name:	Knight & Associates Ltd		Insurance Co.:	RSA		Occupier:		
Our Ref:	SU2003608		Client Name:	Crawford		Address:		
			Technical Mgr:	N Crawford		Address:		
			Email:			Town:		
			Client Ref:			County:		
Monitoring Details			Address:	National Subsidence Unit		Post Code:		
Instruction Date:	8/6/21		Address:	4th Floor 30 St Pauls Square		Tel Home:		
First Reading Date:	12/07/2021		Town:	Birmingham		Tel Work:		
Maximum No Visits:	8		County:			Mobile:		
Anticipated Expiry Date:	Sept '22		Post Code:	B3 1QZ		Other:		
Monitoring Int (Wks):	8		Other Email:	subsidence.monitoring@crawco.co.uk		Other:		

Target Date:															
Reading Date:		12/7/21	13/9/21	4/11/21	10/1/22	3/3/22	11/5/22	5/7/22	7/9/22						
Issue Date:		14/7/21	14/9/21	5/11/21	11/1/22	4/3/22	11/5/22	5/7/22	7/9/22						
Row No.	Point Name	X Co-ordinate	Y Co-ordinate	1	2	3	4	5	6	7	8	9	10	11	12
1	TBM1	0.00	0.00	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000	10.0000				
2		6.40	0.00												
3		6.40	1.00												
4	2	8.90	1.00	10.1070	10.1070	10.1080	10.1080	10.1080	10.1080	10.1070	10.1070				
5	3	8.90	7.00	9.5390	9.5380	9.5400	9.5390	9.5400	9.5390	9.5390	9.5380				
6	4	5.90	7.00	9.3200	9.3200	9.3210	9.3200	9.3210	9.3210	9.3200	9.3200				
7	5	5.90	9.00	9.3830	9.3830	9.3830	9.3820	9.3840	9.3830	9.3820	9.3820				
8	6	3.30	9.00	9.3790	9.3790	9.3800	9.3790	9.3800	9.3790	9.3780	9.3790				
9		3.30	8.00												
10	7	0.00	8.00	9.7830	9.7830	9.7830	9.7830	9.7830	9.7820	9.7820	9.7820				
11		0.00	0.00												
12															
13															
14															
15															
16															
17															
18															
19															
20															
21															
22															
23															
24															
25															
26															
27															
28															
29															
30															
31															
32															




- 07/09/22 Readings taken.
- A common brickcourse could not be followed, subsequently relative data only.
- No further readings are planned

LEVEL MONITORING - RELATIVE MOVEMENT SKETCH

Client: Crawford

Client Ref: 0



Datum Reading	Reading 1 (12/7/21)	Reading 2 (13/9/21)	Reading 3 (4/11/21)	Reading 4 (10/1/22)	Reading 5 (3/3/22)	Reading 6 (11/5/22)
Reading 7 (5/7/22)	Reading 8 (7/9/22)	Reading 9 (0/1/00)	Reading 10 (0/1/00)	Reading 11 (0/1/00)	Reading 12 (0/1/00)	

Notes:
Vertical distorted scale 1: 20

Point labels give level difference of last reading from original datum in mm.

LEVEL MONITORING - RELATIVE SURVEY READINGS

Client: Crawford


Client Ref:

0

Chart Scale 1:1000


1

Difference in reading
mm




2

Difference in reading
mm



3

Difference in reading
mm



Standard Comments for selection in Readings and Sketch Worksheets
User may edit these as appropriate

Standard Comments	
No Comment	
Standard Comment 1	A further visit is due in
Standard Comment 2	No further readings are planned
Standard Comment 3	The Insured requested an update.
Standard Comment 4	Points fitted and readings taken.
Standard Comment 5	

Standard Bullet
●