

G2 KITCHEN



G2 - Window GW30 and shutters



G2 - General view of room looking North

G13 STORE



G13 - Missing plaster finish alongside door



G13 - Moisture damaged plaster to East wall



G2 - General view of room looking South-West



G2 - Joinery on East Wall



G13 - Moisture damaged plaster to South wall

G 2 A N D G 1 3 E X I S T I N G P H O T O S

Butler Hegarty Architects
Unit 3.2, Islington Studios, 159-163 Marlborough Road, London, N19 4NF
tel: 020 72638933 email: mail@butlerhegartyarchitects.co.uk

Bruce Castle Museum
Title: G2 and G13 Existing Photos
Drawing No: 0821921/Su40