

S1 PASSAGE



S1 - View of passage looking South



S1 - View of passage looking North



S1 - Water damage to South wall above door to S2

S2 STUDIO



S2 - Window SW01 to South Wall



S2 - View of room looking West



S2 - Water damage to North wall and ceiling

S3 STUDIO



S3 - Water damage to plaster South wall



S3 - Water damage to plaster North wall

S1, S2 AND S3 EXISTING PHOTOS