

Site Investigation Report

Auger Ref:

88222.3.TSI



Job Information

Client	Sedgwick
Client ref	6857421
Visit date	25/10/2022
Report date	26/10/2022

Job Summary

✓ 1 trial hole undertaken. [Read more.](#)



INVESTORS IN PEOPLE®
We invest in people Gold

Job Information

Overview

Brief

Auger were commissioned by Sedgwick to undertake a site investigation within the area of concern (AOC) at the property.

Findings

Trial Hole Findings

TH1 was able to reach the required depth in the proposed location and reveal the footing. Soil and root samples were taken.

Photographs


Trial Hole 1

Fig 1.1: Trial Hole 1 Location



Fig 1.2: Trial Hole 1 Footing










FRONT OF PROPERTY

This drawing should be used for diagrammatic purposes only. Auger are not responsible or liable for any 3rd party works undertaken using the details outlined in this drawing. Confirmation of the drainage configuration can only be confirmed by excavation or detailed technical survey.

LEGEND


 = Manhole (MH)	 = Blockage / Collapse	 = Lines not camera surveyed	 = Trial hole	 = Shrubs / Bush
 = Inspection Chamber (IC)	 = Soil Vent Pipe (SVP) / WC	 = Lines camera surveyed	 = Borehole	 = Hedge
 = Inspection Point (IP)	 = Combined Waste Gully (CWG) / Foul Waste Gully (FWG)	 = Assumed water mains feed	 = Direction of flow	 = Tree
 = Rainwater Gully (RWG)	 = Rainwater Pipe (RWP)	 = Walls	 = Gate / Door	 = Steps
	 = Fences	 = Building Outline		



Trial Hole Log No.1

Location: Rear middle

Job Ref: 88222.3.TSI

Depth (m)	Symbolic Log	Strata Description	Insitu Tests		Soil Sample	Root Sample
			SV(19)			
0.0		Ground Level				
		Flagstones				
		Brickwork				
0.5		Double Step				
		Concrete				
		Brown silty fine to medium gravelly CLAY	102kpa		Soil @ 0.75m	Root @ 0.75m
1.0			120kpa		Soil @ 1.25m	Root @ 1.25m
1.5			134kpa		Soil @ 1.75m	
2.0			140kpa		Soil @ 2.25m	
2.5			140kpa		Soil @ 2.75m	
3.0		TRIAL HOLE TERMINATED	140kpa			

Unit 3 & 4,
 Heol Aur,
 Dafen Ind Estate,
 Dafen
 Llanelli,
 Carmarthenshire,
 SA14 8QN

***The testing results contained within this report have been performed by GSTL a UKAS accredited laboratory on behalf of Auger.**

 Auger House,
 Cross Lane,
 Wallasey,
 Wirral,
 CH45 8RH

Summary Of Claim Details


Policy Holder	Unknown
Risk Address	Unknown
SI Date	25/10/2022
Issue Date	25/10/2022
Report Date	15/11/2022
Auger Reference	88222.3.2.RSS
Insurance Company	NFU Mutual
LA Claim Reference	6857421
LA Co. Reference	Crawford & Co

This certificate is issued in accordance with the accreditation requirements of the United Kingdom Accreditation Service. The results reported herein relate only to the material supplied to the laboratory. This certificate shall not be reproduced except in full, without the prior written approval of the laboratory.

Checked and approved


15/11/2022

Wayne Honey






Test Operator
Jason Smith



PLASTICITY CHART FOR CASAGRANDE CLASSIFICATION
BS 5930:1999+A2:2010



Modified Plasticity Index (PI) <10 : Non Classified
 Modified PI = 10 to <20 : Low volume change potential (LOW VCP)
 Modified PI = 20 to <40 : Medium volume change potential (Med VCP)
 Modified PI = 40 or greater : High volume change potential (HIGH VCP)

The Atterberg Limits May also be used to classify the volume change potential of fine soils using the National House building system, as given in the NHBC's Standards Chapter 4.2 (2003) "Building Near Trees"

Test Operator

Jason Smith


GSTL Contract Number	62237	
Risk Address	Unknown	
Auger Reference	88222.3.2.RSS	
Remarks	D - Disturbed (Recompacted 2.5kg Rammer), U - Undisturbed Sample	

TH Trial Hole	Depth (m)	Filter Paper Location	Filter Paper	Sample Prep Method	Test Duration (Days)	Water Content (%)	Soil Suction Pk (kPa)	Average Soil Suction Pk (kPa)	Cumulative Heave Potential (mm) from bottom of the hole
TH1	0.75	Top	I	D	5	30.9	824	813	61
TH1		Middle	II	D	5	31.0	815		
TH1		Bottom	III	D	5	31.1	799		
TH1	1.25								
TH1									
TH1									
TH1	1.75	Top	I	D	5	23.7	2320	2320	33
TH1		Middle	II	D	5	23.6	2350		
TH1		Bottom	III	D	5	23.8	2310		
TH1	2.25								
TH1									
TH1									
TH1	2.75	Top	I	D	5	26.4	1590	1570	19
TH1		Middle	II	D	5	26.4	1580		
TH1		Bottom	III	D	5	26.5	1550		

Heave potential is calculated from the bottom of the hole and heaves above the bottom of the hole are reported as a cumulative value.

The values reported for heave above only apply to the strata the suction and plasticity have been performed on. The shallowest depth reported is assumed to be a strata thickness to GL and Heave is calculated based on that layer thickness, if the next sample is in 0.5m increments the heave is calculated based on the layer thickness of 0.5m and depths 1m from the sample above will include heave over 1m.

Consideration should be made for other stratas where values are not reported and when working out the heave potential over the entire trial hole.



Test Operator

Jason Smith



Richardson's Botanical Identifications

Root identification
Vegetation surveys
Tree/Building investigations
Plant taxonomy

Auger Solutions

Auger House

Cross Lane

WALLASEY

Wirral CH45 8RH

Dr Ian B K Richardson
BSc, MSc, PhD, MRSB, FLS
James Richardson
BSc (Hons. Biology)

Enterprise House
49-51 Whiteknights Road
Reading
RG6 7BB

Tel: (0118) 986 9552 (Direct line)
E-mail: richardsons@botanical.net
Web: www.botanical.net

Your ref: 88222-3-1

Our ref: 84/4913

12/11/2022

Dear Sirs

Root ID

The samples you sent in relation to the above on 25/10/2022 have been examined. Their structures were referable as follows:

TH1, 0.75m		
3 no.	Examined root: similar in many ways to QUERCUS (Oak) or the related CASTANEA (Sweet Chestnut). Less than 0.8mm in diameter.	Alive, recently*.
TH1, 1.25m		
1 no.	Examined root: QUERCUS (Oak) or the related CASTANEA (Sweet Chestnut). Also under 0.8mm in diameter.	Dead*.
3 no.	Unfortunately all with insufficient cells for identification.	

Click here for more information: [CASTANEA](#) [QUERCUS](#)

I trust this is of help. Please call us if you have any queries; our Invoice is enclosed.

Yours faithfully

Dr Ian B K Richardson

* Based mainly on the Iodine test for starch. Starch is present in some cells of a living woody root, but is more or less rapidly broken down by soil micro-organisms on death of the root, sometimes before decay is evident. This result need not reflect the state of the parent tree.

** Try out our web site on www.botanical.net **