

LEVEL MONITORING

for Subsidence Management Services

36 Grasmere Road, London, N10 2DJ

Client:	Subsidence Management Services
Client Contact:	Ian Domigan
Claim Number:	700015200
Client Reference:	IFS-LBG-SUB-22-0102137
Policy Holder:	Ms Sally Eichner
Report Date:	7 March 2023
Our Ref:	M20400


Level Monitoring Readings

The following table shows the reading levels of the various Level Monitoring Station points.

Date	1	2	3	4	5	6	7	8
12/01/2023	10.0000	9.9942	9.8270	9.9913	10.3382	10.0429	9.9679	9.8919
06/03/2023	10.0000	9.9945	9.8272	9.9912	10.3383	10.0430	9.9687	9.8927



Level Monitoring Difference Graphs

The following graphs display the progressive movement that each Level Monitoring Station recorded at each separate site visit date to give an overall look at how much the property is moving.



Level Monitoring Displacement Map

The following image shows an isometric representation of the movement of the property, based on the Level Monitoring Stations that were installed.



FRONT

Site Visit Notes

Manhole in front of property is the TBM, assume a value of 10.0000. Please advise if DD is required.